	NM OTT CONS Draw, DD Artesia, NM	cl
June 1990) DEPARTME	ITED STATES NT OF THE INTERIOR LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. LC 029426-B
Do not use this form for proposals to d	AND REPORTS ON WELLS rill or to deepen or reentry to a different reserv OR PERMIT—" for such proposals	6. If Indian, Alkotee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation NA
V Oni Gas Well Well Other		8. Well Name and No.
2 Name of Operator		H.E. WEST ''B'' #53
SOCORRO PETROLEUM COMPANY 3 Address and Telephone No.		9. API Well No.
P.O. BOX 37, LOCO HILLS, NEW MEXICO 88255 (505) 677-3223		30-015-27148 10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey E	EATCO 00233 (303) 077-3223	GRAYBURG-JACKSON POOL 11. County or Parish, State
1350' FNL & 1250' FEL, SEC 9,	T17S, R31E UNIT H	EDDY, NEW MEXICO
2 CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACT	ION
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Plugging Back	New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Casing Repair Altering Casing Other PERF, ACIDIZE & F	RAC Dispose Water (Note: Report results of makiple completion on Well
	L Il pertinent details, and give pertinent dates, including estimated date of s cal depths for all markers and zones pertinent to this work.)*	Completion or Recompletion Report and Log form) starting any proposed work. If well is directionally drilled.
12-93 MIRU well service unit. RIH with 4-3/4" bit 3238', 3282'-3290', 3318'-3332', 3344-3348', RIH. Set RBP @ 3490'.	and scraper to clean 5-1/2" csg to 3500'. Perforate in ac , 3360'-3364', 3392'-3394', 3418'-3420', 3434-3438' (total	
3-93 Rig up to acidize. Set pkr @ 3450', test RBP well head and BOP to 3000#. Trap 1000# press brine, total of 1150# of salt. Had good bloc 2070#. Turn well to lined pit. Blew well do 500' feed in. Plow to tank on 20/64" choke.	set @ 3490' to 3150#. Circulate well clean with 10#/gal l ure on csg annulus. Acidize well with 5250 gal 7-1/2% MEP king action through out job. Max treating pressure 3170 wn. Recover 10 bbl load water. Rig up. Swab back 22 bbl SWI.	brine. Pull up set pkr @ 3150'. Test csg, B acid. Drop 5 salt blocks mixed in gelled , avg pressure of 2930#, AIR 6.5 B/M, ISIP load to S/N at 3150'. Wait 30 minutes had
15-93 Open well to tank on 20/64" choke had small : 3380 swab Premier perfs 3392'-3438'. Recove and RBP. RIH to 4100', circulate well clean	flow. Swab perfs 3228' to 3420'. Recover 24 bbl load wat r 24 bbl load water, 0% oil cut. Swab to S/N @ 3380' wai . PU and set RBP @ 3450' test to 2500#. POH. Start RIH	er O% oil cut. Release pkr, RIH set pkr @ t 30 minutes, no fluid entry. Release pkr w/2-3/8" tbg. SWI.
 Circulated hole clean w/brine water. Test surface lines to 46004. 	w/2-3/8" monitoring string to 3248' with blast joint at s 192 holes) down 5-1/2" x 2-3/8" csg annulus w/48,000 gal (uid (67% volume crude oil and 33% volume gelled water). ess 3029#, AIR 21 BPM, ISIP 2618#. 1111 total bbl load (
$ \rightarrow $	Continued on Back	
I hereby certify that the top come to true and covect	PRODUCTION MANAGER	12-20-93
This space for Federal or State office why	Title	Dete
Approved by	TitleACCEPTED PO	Dete

*See Instruction on Reverse Side

- 11-17-93 Open well w/2100# SITP to frac tank. Flow 200 bbl load on 1" choke. Well stopped flowing sand. Installed adjustable choke. Flow well on 23/64" choke. Well flowing with 150# FTP.
- 11-18-93 Well flow to frac tank in 24 hours, 148 BO and 281 BW. PTP 501-2001 on 23/64"choke. Rig up pump truck and circulate well with 80 bbls brine water. RIH, tag frac sand @ 3438'. Rig up pump truck, wash frac sand to RBP @ 3450'. Release plug, POH, and lay 2-3/8" tbg and RBP down. RIH with 2-7/8" tbg. Leave well open to frac tank
- 11-19-93 Flow 14 hours recovered 0 BO and 40 BW. Well had 200# on csg. Blow well down to tank. Remove BOP and install well head. RIH w/pump and rods. Left well pumping.
- 11-29-93 MIRU pulling unit to change BHA to prevent gas locking. POH with rods and tbg. RIH. Set tbg below perfs. Left well pumping.

(India)

- 11-30-93 Pump 16 hours. 12 BO and 30 BW.
- 12-08-93 First day of production after recovering load. Pump 24 hours. 23 BO and 49 BW.