

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OIL CONSERVATION DIV

811 S. 1st ST. FORM APPROVED
ARTESIA, NM 88210-2634 Budget Bureau No. 1004-0135
Expires March 31, 1993

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
DEVON ENERGY CORPORATION (NEVADA) ✓

3. Address and Telephone No.
20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 236-3611

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
15'FSL & 2525'FWL of Section 3-T17S-R31E

5. Lease Designation and Serial No.
LC-029426B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
H.E. West "B" #57

9. API Well No.
30-015-27317

10. Field and Pool, or Exploratory Area
Grayburg-Jackson Field

11. County or Parish, State
Eddy County, NM


CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
☒ Notice of Intent	☐ Abandonment	☐ Change of Plans
☐ Subsequent Report	☒ Recompletion	☐ New Construction
☐ Final Abandonment Notice	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut-Off
	☐ Altering Casing	☐ Conversion to Injection
	☐ Other _____	☐ Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Recomplete and test the Seven Rivers formation as follows:

1. Temporarily abandon the Grayburg/San Andres formations with CIBP.
2. Selectively perforate the Seven Rivers interval.
3. Acidize and swab test.
4. Run production tubing, pump and rods and put on production test for ±6 months.



14. I hereby certify that the foregoing is true and correct

Signed Randy Jackson Title District Engineer Date July 10, 1996
(This space for Federal or State office use)

Approved by Orig. Signed by Adam Salameh Title _____ Date 7/23/96
Conditions of approval, if any: