

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	TOP		
				NAME	MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	384	545	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
Salado	545	1396				
Tansill	1396	1554				
Yates	1554	1858				
Seven Rivers	1858	2483				
Queen	2483	2874				
Grayburg	2874	3194				
San Andres	3194	4155 (TD)				
		DEPTH				
		3166'-3383'				
		3166'-3503'				
		2902'-3118'				
		Acidized w/2100 gals 15% HCl acid. Attempted to frac. Pressured out on pad (6552 gals Vik I-30 gel) Acid w/2525 gals 15% HCl acid. Frac'd w/20,500 gals x-link gel + 50,000# 20/40 Brady sand + 28,000# SLC resin coated sand.				