

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP		BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
						MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	324	514	514 1290 1440 1742 2356 2746 3074 3765 (TD)	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
Salado	514	1290					
Tansill	1390	1440					
Yates	1440	1742					
Seven Rivers	1742	2356					
Queen	2356	2746					
Grayburg	2746	3074					
San Andres	3074	3765 (TD)					
			DEPTH	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)			
		2754' - 3214'		Acidized w/4000 gals 15% HCl acid. Frac'd w/44,000 gals gel + 70,000# 16/30 Brady sand + 70,000# 12/20 Brady sand.			