Form 3160-5 (June 1990)

## UNIT STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

O ONSERVATION DIV 81 1 3. 1st ST. ARTESIA, NM 88210-2834 FORM APPRO

0/54

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals		5. Lease Designation and Serial No.
		LC-029435B
		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well  Oil Gas Other Well Other		
2. Name of Operator DEVON ENERGY CORPORATION (NEVADA)		8. Well Name and No.
3. Address and Telephone No. 20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611		J.L. Keel "B" #86  9. API Well No.
		30-015-28484
4. Location of Well (Footage, Sec., T., R., M., or Survey Des	scription)	10. Field and Pool, or Exploratory Area
49'FSL & 2520'FWL of Section 5-T17S-R31E		Grayburg-Jackson Field
		11. County or Parish, State
		Eddy County, NM
CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REP	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion	New Construction
Suosequent Report	☐ Plugging Back☐ Casing Repair	Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
13 Describe Proposed or Completed Operations (Clearly state all per	inent details, and give pertinent dates, including estimated date of starting any	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
locations and measured and true vertical depths for all markers	and zones pertinent to this work.)*	proposed work. if well is directionally drilled, give subsurface
Recomplete and test the Seven Rivers	formation as follows:	JUL 12 7992
1. Temporarily abandon the Grayburg	g/San Andres formations with CIBP.	SHIM BELLE
2. Selectively perforate the Seven Ri	-	hs. (20/8)
3. Acidize and swab test.		JUL , 10 %
		hs. \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
4. Run production tubing, pump and	rods and put on production test for $\pm 6$ mont	hs.
		S NM
	grapher and the second section of the sectio	hs. Now Mexico
	HU 0 70	
	JUL 2 5 1	1995
		565 (A. J.
14. I hereby certify that the foregoing is true and correct	Pandy Indiana	C.A.
Signed Jones Gordon	Randy Jackson Title District Engineer	Day 10 1004
(This space for Federal or State office use)	Title <u>District Engineer</u>	Date July 10, 1996
Approved by	mat. See See a see a see a see a see	7/27/2
Conditions of approval, if any:	Title	Date 7/23/96