

**MACK ENERGY CORPORATION
GJ WEST COOP #138
2615 FSL 1859 FWL Sec 28, TWP 17S, R 29E
UNIT LETTER K**

PERFS: 3222,3239,3245,3271,3282,3304,3308,3326,3330,3335,3440,3441,3443,3543,3548,3555,3561,3580,3637,3639,3641,3741,3743,3750,3755,3757,3820.

6-13-95 RU-pickup 6-3 1/8" Drill collars 4 3/4" LH-1 bit & 5 1/2 csg scraper.

6-14-95 RIH w/workstring tag ES cementer @ 3802' & drill out in 23 min. RIH & tag bottom @ 4572'. POH & lay down drill collars. RU-HLS & run logs. Perforate 3222-3820' (27 holes).

6-15-95 Acidize perfs 3222-3820' w/2000 gals 15% NE. Swab test zone

6-16-95 Pump Hot acid job. 54,000 gals 40# heated gel. 32,000 gals 20% heated acid. 5000 gals. cold 15% acid & 4000 gals fresh water flush.

6-19-95 Unset RTTS & POH laying down workstring. RIH w/2 7/8" prod. tbg. Run to bottom & wash block & balls off bottom Land tbg. @ 3877. Ran rods and put well on pump