Form 3160-5 (November 1983) (Formerly 9-331)

UNITED _ (ATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE *
(Other Instructions on reverse side)

Budget Bureau No. 1004-0135 Expires August 31, 1985 015/

BUREAU	J OF LAND MANAGEMENT	reverse side)			
			5. LEASE DESIGNATION AND SERIAL NO. LC-029418-A		
SUNDRY NOTICES AND REPORT STORINGES Division			6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
(Do not use this form for pro	pposals to drill or to deepen or plug back o a	Misse River voir.	0. 11 111151	AN, ALLOTTLE OR TRI	DE NAME
Use APPLI	CALIUN FUR PERMIT TOT SIICH INTONOS:	31S)			
OIL GAS OTHER			7. UNIT AGREEMENT NAME		
WELL WELL			Skelly Unit		
2. NAME OF OPERATOR			8. API WE	LL NO.	
The Wiser Oil Company NOV - 1 1950			30-015-28947		
3. ADDRESS OF OPERATOR			9. WELL NO.		
P.O. Box 2568 Hobbs, New Mexico 88241			201		
LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers		
1272' FSL & 45' FWL			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
Secc. 14-T17S-R31E Unit M			SURV	ET OK AKEA	
			Sec. 14-T17S-R31E		
14. PERMIT NO 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3882'				TY OR PARISH	13. STATE
	<u> </u>		Edd	<u>y</u>	NM
16. Check	Appropriate Box to indicate Natur	e of Notice, Report, or Other	r Data		
NOTICE OF INTENTION TO:			BSEQUENT REPORT OF:		
TEST WATER SHUT OFF	PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT		ALTERING CASING	; <u> </u>
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING		ABANDONMENT *	
REPAIR WELL CHANGE PLANS (Other) Perforate & Acid					
			of multiple completion on Well eletion Report and Log form.)		
17. DESCRIBE PROPOSED OR COMPLET	TED OPERATIONS: (Clearly state all pertin	nent details, and give pertinent dates,	including es	timated date of starting any	
proposed work. If well is directionally	drilled, give subsurface locations and measu	ared and true vertical depths for all m	arkers and z	ones pertinent to this work.	•
09/26/96 Halliburton perforated San A	Andres Three Fingers f/3798', 99', 3801', 02	2', 03', 13', 14' & 15' w/1 SPF (8 ho	oles).		
09/27/96 Halliburton acidized San Andin formation. MTP 4750#@	dres Three Fingers w/1200 gals. 15% NE-FF g 4 bpm. ATP 3850# @ 3.5 bpm. ISIP 334	E acid + 16 ball sealers. Formation b 0#. 5 min. 2750#. 10 min. 2555#.	roke @ 295 15 min. 239	4#. Balled out w/16 bbls. a 9#.	acid
09/30/96 Halliburton perforated San A Formation would not break @	Andres Vacuum f/3570', 71', 74', 75', 76', & (2) 5400#. Re-spotted acid & formation would	th 78° w/1 SPF (6 holes). Acidized w d not break. Respotted acid. Reverse	/1000 gals. ed circ. & Po	15% NE-FE acid + 12 ball DH.	sealers.
acid + 24 ball sealers. Forma	Andres Vacuum f/3570', 71', 74', 75', 76' tion broke @ 4037#. MTP 3434# @ 4.3 b f/3332', 33', 34', 3439', 40', 60', 61', 62',	pm. ATP 2650# @ 4 bpm. ISIP 19-	45#. 5 min.	1796#. 10 min. 1739#. 1	NE-FE 5 min.
	15% NE-FE acid & acidized Grayburg w/23 P 4495# @ 4.3 bpm. ATP 2900# @ 3.8 bp				alled out
18. I hereby certify that the foregoing is true a	ind correct.				
SIGNED Mary Jo Turney	TITLE Completion	n Department	DATE _	October 15, 1996	
(This space for Federal or State office use)				-	
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE		_ DATE_	Marie Constitution	
and the second s		n On Reverse Side		0 CT 3 0 l	996