Form 3160-5 (November 1983) (Formerly 9-331)

statements or representations as to any matter within its jurisdiction.

## UNITE STATES DEPARTMENT OF THE INTERIOR

N.M. O'LCons. Division

SUBMBINTRICATE Street Bureau No. 1004-0135 (Other reside), NM 8821-0:-280-4t 31, 1985

اح	5	1
) I ( )		

BUREAU OF LAND MANAGEMENT		5. LEASE DESIGNATION AND SERIAL NO. LC-029418-A			
SUNDRY NOTICES AND REPORTS ON WELLS		6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.		, , , , , , , , , , , , , , , , , , , ,	22.11.21.21		
	ATION FOR PERMIT - " for such propos				
1.	OTHER		7. UNIT AGREEMENT NAME		
OIL GAS WELL OTHER		Skelly Unit			
2. NAME OF OPERATOR		8. API WELL NO.			
The Wiser Oil Company		30-015-28949			
3. ADDRESS OF OPERATOR		9. WELL NO.			
P.O. Box 2568 Hobbs, New Mexico 88240 (505) 39259797		228			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.		10. FIELD AND POOL, OR WILDCAT			
See also space 17 below.) At surface  1326' FNL & 1317' FWL		Grayburg Jackson Seven Rivers			
		087884	11. SEC., T., R., M., OR BLK. AND		
Unit E			SURVEY OR AREA		
			Sec. 23-T17S-R31E		
14. PERMIT NO	15. ELEVATIONS (Show whether DF, I	RT. GR. etc.)	12. COUNTY OR PARISH	13. STATE	
	. 3868'		Eddy County	NM	
16. Check A	Appropriate Box to indicate Natur	e of Notice Report or Other		14141	
io.	ppropriate Dox to midicate Matur	l	Data		
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPORT OF:		
TEST WATER SHUT OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL		
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT *		
REPAIR WELL	CHANGE PLANS	(Other) Added perforations to			
(Other) (Note: Report results of Completion or Recom			oletion Report and Log form.)		
	FD OPERATIONS: (Clearly state all perti	I			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)					
08/24/00 MIRU Key WS. NU BOP's. RIH w/4-3/4" bit, DC's & 2-7/8" tbg. Tagged @ 3369'. Drld. cmt. f/3369'-3382'. Drld CIBP @ 3382'. Pushed CIBP to 3452'. Resume drlg. Circulate clean. RD swivel.					
08/25/00 Drld. scale to 3563'. POH. LD collars. RU Computalog & perforated Upper Jackson f/3804'-11' & 3827'-46' w/2 SPF (56 holes). RD WL. RIH w/RBP & pkr. Set RBP @ 3889'. Set pkr. @ 3386'.					
08/28/00 Acidized Jackson perfs. 3804'-3846' w/3000 gals. 15% NE-FE acid & 3,000# rock salt. Good block action. Blocked off perfs. w/2500 gals. in formation. ATP 3000#@ 1.8 bpm. MTP 3600#@ 2.4 bpm. ISIP 2650#. 5 min. 2450#. 10 min. 2420#. 15 min. 2400#. Shut in for 1 hr. RU swab.					
08/29/00 Released pkr. RIH to 3840' & tagge	ed fill. Set CIBP @ 3500'. RIH w/cmt. re	tainer to 3372'. Pumped 25 bbls. wa	tter. Set retainer @ 3372'.		
08/30/00 Squeezed Grayburg perfs. 3414'-82'	'w/150 sks. Class "C" neat & 50 sks. Clas	s "C" w/3% CaCl2. RIH w/4-3/4" b	oit, DC's & 2-7/8" tbg.		
08/31/00 Tagged @ 3362'. Drid. cmt. to 337	2'. Drld. retainer. Drld. soft cmt. to 3442'	. Pressured up on csg. to 800#,			
09/01/00 Drld. cmt. & CIBP at 3500'. LD columit. Put well back to pumping to B		. NU WH. SN @ 3907'. RIH w/2-	1/2" x 1-1/2" x 16' pump and rods. Set	Cabot pumping	
18. I hereby certify that the foregoing is true an	d correct.				
SIGNED Mary Jo Junner	TITLE Production	Tech II	ACCEPTED FOR RE	CORD	
(This space for Federal or State office use)					
A BRDOVED BY	тт е		batte		
APPROVED BY	TITLE		- PATE   MAY 23 2001	<del></del>	
<del> </del>					
		n On Reverse Side	ALEXIS C. SWOBO PETROLEUM ENGIN	EER	
Title 18 U.S.C. Section 1001, makes it a crime	for any person knowingly and willfully to	make to any department or agency of	f the United States any false, fictitious or	fraudulent	

TAPA CAS TO MESUR BOTTO THE MORE

3831 KYX ST W 8:52

PECENED