Form 3160-5 (June 1990)

representations as to any matter within its jurisdiction.

N.M. Oil Cons. [sion

615P

UN. LED STATES 811 S. 1st Street FORM APPROVED DEPARTMENT OF THE INTERIOR AFTESIA, NM 88210-2834 Expires: March 31, 1993

and the second s	Lease Designation and Serial No.
Do not use this form for proposals to drill or to deepen or reentry to a different reservice. Use "APPLICATION FOR PERMIT" for such proposals	LC 029420A 6. Pandian, Alottee or Tribe Name
SUBMIT IN TRIBUCATE S RECEIVED	7. If Unit or CA, Agreement Designation SKEYLY UNIT
1. Type of Well: OIL GAS OTHER HORIZONTAL	SKELLY UNIT A 8. Well Name and Number SKELLY UNIT
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	902
397-0405 Address and Telephone No. 205 E. Bender, HOBBS, NM 88240	9. API Well No. 30-015-29322
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, Exploaratory Area
Unit Letter E: 1650 Feet From The NORTH Line and 990 Feet From The NORTH Z509	HENSHAW WOLFCAMP SE 11. County or Parish, State
WEST Line Section 15 Township 17-S Range 31-E $17-S$ $3/-E$	EDDY , NM
Check Appropriate Box(s) To Indicate Nature of Notice, F	Report, or Other Data
	TYPE OF ACTION
ACCEPTED FOR RECORD Abandonment Recompletion Plugging Back Casing Repair Attering Casing OTHER: HORIZONTAL COMP	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection LETION Dispose Water
PIM	(Nate: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
10-06-00: MIRU KEY #319 SERV UNIT. 10-07-00: REL TAC. TIH TO 8500'. RD SU. 10-08-00: TIH W/CIBP & SET @ 8430'. TEST CSG TO 1000 PSI. 10-10-00: SET RIG ON LOCATION. 10-11-00: MIRU KEY #118 HORIZONTAL RIG. NUBOP.	
10-12-00: TIH W/DP TO 8430. TAG CIBP. TIH W/WHIPSTOCK. RUN GYRO. ORIENT TO 132 DE 8725,78,8840,52,9029,74,92. CUT THROUGH FOR SIDETRACK FR 8999-9029, DRLG 9029-31,32 18,9565,82,9629,60,75,91,9720,26,54,64,9850,56,70,9913,23,45,55,10071,81,10149,69,90,10261,794,10526,34. TD CALLED @ 1500 10-20-00.MD = 10,534. TEST TDT LOG - WOULD NOT WORK. HOOK, BMPR SUB, JARS & TIH. CATCH WHIPSTOCK. 10-23-00: TIH W/RBP & SET @ 8308'. TEST PLUG TO 800 PSI. NDBOP. REL RIG @ 1800 HRS 10-25-00: SET PIPE RACKS. TIH TO 8225' W/REYR HEAD. 10-26-00: REL PLUG. TIH W/2 7/8" TBG & SUBS. SN @ 8283.59'. TRY TO SET PKR. SET & NU 10-29-00: STIMULATE WOLFCAMP FORMATION W/60,000 GALS 20% HCL & 40,000 GALS WF-10-30-00: MIRU SWABBING UNIT. SWABBING. 11-01-00: PUMP 80 BBLS FW DN TBG & KILL WELL. ND FRAC TREE. REL PKR. 11-02-00: TIH & KNOCK CIBP SET @ 8430 DN HLE TO 11870. SET TAC. NDBOP. NUWH. RU P 11-10-00: ON 24 HR OPT. PUMPED 374 BO, 169 BW, 364 MCF. FINAL REPORT	2,37,62,9124,44,9303,13,38,45,76,9408, 76,10336,46,59,65,10416,45,66,79, LOG LATERAL W/TDT.PU WHIPSTOCK,, 10-22-00. FREE. TEST BACKSIDE TO 1000 PSI.
10-12-00: TIH W/DP TO 8430. TAG CIBP. TIH W/WHIPSTOCK. RUN GYRO. ORIENT TO 132 DE 8725,78,8840,52,9029,74,92. CUT THROUGH FOR SIDETRACK FR 8999-9029, DRLG 9029-31,32 18,9565,82,9629,60,75,91,9720,26,54,64,9850,56,70,9913,23,45,55,10071,81,10149,69,90,10261,794,10526,34. TD CALLED @ 1500 10-20-00.MD = 10,534. TEST TDT LOG - WOULD NOT WORK. HOOK, BMPR SUB, JARS & TIH. CATCH WHIPSTOCK. 10-23-00: TIH W/RBP & SET @ 8308'. TEST PLUG TO 800 PSI. NDBOP. REL RIG @ 1800 HRS 10-25-00: SET PIPE RACKS. TIH TO 8225' W/REYR HEAD. 10-26-00: REL PLUG. TIH W/2 7/8" TBG & SUBS. SN @ 8283.59'. TRY TO SET PKR. SET & NU 10-29-00: STIMULATE WOLFCAMP FORMATION W/60,000 GALS 20% HCL & 40,000 GALS WF-10-30-00: MIRU SWABBING UNIT. SWABBING. 11-01-00: PUMP 80 BBLS FW DN TBG & KILL WELL. ND FRAC TREE. REL PKR. 11-02-00: TIH & KNOCK CIBP SET @ 8430 DN HLE TO 11870. SET TAC. NDBOP. NUWH. RU P	2,37,62,9124,44,9303,13,38,45,76,9408, 76,10336,46,59,65,10416,45,66,79, LOG LATERAL W/TDT.PU WHIPSTOCK,, 10-22-00. FREE. TEST BACKSIDE TO 1000 PSI. 130.