

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. Oil Cons. Division

811 S. 1ST

ARTESIA, NM 88210-2934

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NMOC-289426 B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Arco 10 Federal #1

9. API Well No.

30-215-29370

10. Field and Pool, or Exploratory Area

Wildcat-Cedar Lake Devonian

11. County or Parish, State

Eddy County, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Burns Operating Company

3. Address and Telephone No.

P.O. Box 97525 Wichita Falls, Tx 76309

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FEL & 660' FSL

817 322 5470
940-322-5470
990/5 2310/W
10-17-31

W. N

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drill 7 7/8" hole to total depth of 12500'. Run electric logs and plugged and abandoned well in the following manner, per Mr. Joe Lara, BLM.

Plug #1:	12500-12300'	200' Plug	60 sx. Class "H" Neat	Bottom Plug
Plug #2	11600-11500'	100' Plug	30 sx. Class "H" Neat	Top of Chester
Plug #3	11100-11000'	100' Plug	"	Top of Morrow
Plug #4	9700-9600'	100' Plug	"	Top of Penn-Canyon
Plug #5	8300-8200'	100' Plug	"	Top of Wolfcamp
Plug #6	7200-7100'	100' Plug	"	Top of Abo
Plug #7	5100-4900'	200' Plug	60 sx. Class "H" Neat	Across 8 5/8 Shoe. Tagged at 4955'.
Plug #8	2700-2600'	100' Plug	30 sx. Class "H" Neat	Base of Salt
Plug #9	650-550'	100' Plug	"	Across 13 3/8" Shoe.
Plug #10	60'- Surface	60' Plug	15 sx. Class "H" Neat	Surface plug.

BLM-Cathey Queen witness plugging. Rig down and move out ZiaDril #2. Remove wellhead, fill cellar and installed regulation dry hole marker. Remediate location and reseed with appropriate mix. Filled in and leveled pits.

14. I hereby certify that the foregoing is true and correct

Signed

Title Agent

Date 04/02/97

(This space for Federal or State office use)

ORIG. SGD. GARY GOURLEY

Approved by

Title

Date

AUG 18 1995

Conditions of approval, if any: