

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE *
(Other Instructions on
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals.)

Oil Cons. Division

311 S. 1st Street
Artesia, N.M. 88210-2834

5. LEASE DESIGNATION AND SERIAL NO.
LC-029419-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Skelly Unit

8. API WELL NO.
30-015-29762

9. WELL NO.
213

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson 7-Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 22-T17S-R31E

1. ☒ OIL ☐ GAS ☐ OTHER

2. NAME OF OPERATOR
The Wiser Oil Company

3. ADDRESS OF OPERATOR
P.O. Box 2568 Hobbs, New Mexico 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

40' FNL & 1220' FEL
Sec. 22-T17S-R31E
Unit A

RECEIVED
OCD - ARTESIA

14. PERMIT NO

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3867'

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☒

(Other) Perforate & Acidize

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

09/09/97 Halliburton perforated San Andres Three Fingers and Upper Jackson f/3698', 99', 3700', 12', 13', 53', 61', 63' & 73'-87' w/1 SPF (23 holes).

09/10/97 RIH w/5-1/2" Baker pkr. on 2-7/8" tbg. & set @ 3594'. HES reversed 20 bbls. into tbg. Acidized Three Fingers and Jackson perms/ w/3400 gals. 15% NE-FE acid + 46 ball sealers. Formation broke @ 3925#. ATP 3275# @ 3.2 bpm. MTP 3523# @ 4.3 bpm. Balled out @ 5710#. ISIP 2610#. 5 min. 2217#. 10 min. 2130#. 15 min. 2071#.

09/11/97 Halliburton perforated San Andres Vacuum f/3505', 06', 07' & 16'-28' & 1 extra w/1 SPF (17 holes). Set Baker RBP @ 3550'. Spotted acid & set pkr. @ 3400'. Acidized San Andres Vacuum perms/ w/2500 gals. 15% NE-FE acid + 34 ball sealers. Formation broke @ 2764#. ATP 2700# @ 4 bpm. MTP 3215# @ 4.3 bpm. Balled out w/4550#. ISIP 2185#. 5 min. 2088#. 10 min. 2056#. 15 min. 2030#.

09/12/97 Set RBP @ 3493'. POH w/tbg. & pkr. Halliburton perforated Grayburg f/3290', 91', 92', 93', 3330', 31', 36', 58', 59', 60', 98', 99', 3425', 26', 27', 28', 29', 62', 63', 72' & 73' w/1 SPF (21 holes). RIH w/5-1/2" Baker Pkr. on 2-7/8" tbg. to 3450'.

09/15/97 Spotted acid & set pkr. @ 3180'. HES broke down & acidized Grayburg perms. f/3290'-3473' w/3100 gals. 15% NE-Fe acid & 42 ball sealers. Formation broke @ 2984#. ATP 2680# @ 4.2 bpm. MTP 2932# @ 4.9 bpm. Balled out w/4546#. ISIP 2245#. 5 min. 2015#. 10 min. 1981#. 15 min. 1960#. POH & LD tbg.

18. I hereby certify that the foregoing is true and correct.

SIGNED Mary Jo Turner TITLE Completion Department DATE October 30, 1997

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instruction On Reverse Side