		ALL ALL CAR	Mada to the
		M.M. Oil Con.	
mi 3160-5 JNE 1960)	UNITED STATES DEPARTMENT OF THE INTERI	SR. 5. 181	Budget Bureeu No. 1004-0136
	BUREAU OF LAND MANAGEME	NT	J-2834 Expires March 31, 1993 5. Lease Designation and Serial No.
	SUNDRY NOTICES AND REPORTS ON	WELLS	LC-060529
Do not	use this form for proposals to drill or to deepen or reentry		6. If Indian, Alkottee or Tribe Name
	Use "APPLICATION FOR PERMIT " for such p	roposals.	
	SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
Type of Weil			
	Other		
Name of Operator		×.	8. Well Name and No. Beeson "F" Federal No. 24
Shahara O Address and Telephone No.			9. Well API No.
	:Kay, Carlsbad, NM 88220	RETENT	30-015-29878
505-885-54		HE FER	10. Field and Pool, or Exploratory Area Loco Hills Queen Grayburg SanAndres
Location of Well (Footage, Sec., T., R., M.,	, or Survey Description)	··· COIA	11. County or Parsh, State
1340' FNL	& 904' FEL, Unit H		
	, T17S, R30E	<u></u>	Eddy County, New Mexico
C	HECK APPROPRIATE BOX(s) TO INDICATE	NATURE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE C	TYPE OF SUBMISSION TYPE		PE OF ACTION
	of Intent	Abandonment	Change of Ptans
Notice o	a niterik	Recompletion	New Construction
XSubseq	uent Report	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
Final At	bandonment Notice	X Altering Casing	Conversion to Injection
			Dispose Water
		<u> </u>	(Note: Report results of multiple completion on Well
			Completion or Recompletion Report and Log form.)
	tions (Clearly state all pertinent details, and give pertinent dates, inc		
	tions (Clearly state all pertinent details, and give pertinent dates, inc asured and true vertical depths for all markers and zones pertinent		
subsurface locations and mea	asured and true vertical depths for all markers and zones pertinent i		
subsurface locations and mea	asured and true vertical depths for all markers and zones pertinent i		
subsurface locations and mer 2/06/98 Drill 12 1/4" hole to T	asured and true vertical depths for all markers and zones pertinent i		
subsurface locations and mer 2/06/98 Drill 12 1/4" hole to T	asured and true vertical depths for all markers and zones pertinent i		
subsurface locations and mer 2/06/98 Drill 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE.		
subsurface locations and mer 2/06/98 Drill 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg.		
subsurface locations and mer 2/06/98 Drift 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good.	to this zone.)*	roposed work. If well is directionally drilled, give
subsurface locations and mer 2/06/98 Drift 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE.	to this zone.)*	roposed work. If well is directionally drilled, give
subsurface locations and mer 2/06/98 Drift 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE.	o this zone.)*	TO COLLEGIASS
subsurface locations and mer 2/06/98 Drift 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good.	o this zone.)*	roposed work. If well is directionally drilled, give
subsurface locations and mer 2/06/98 Drift 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 2/12/98 Perf 28 holes from 2	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE.	o this zone.)*	TO COLLEGIASS
subsurface locations and mer 2/06/98 Drift 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE.	o this zone.)*	Toposed work. If well is directionally drilled, give
subsurface locations and mer 2/06/98 Drift 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE.	o this zone.)*	TO COLLEGIASS
subsurface locations and mer 2/06/98 Drift 12 1/4" hole to 1 2/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE.	o this zone.)*	Toposed work. If well is directionally drilled, give
subsurface locations and mer 12/06/98 Drill 12 1/4" hole to 1 12/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2 12/13/98 Frac w/43000gls De	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE. etta & 75000# 16/30 sand.	o this zone.)*	Toposed work. If well is directionally drilled, give
subsurface locations and mer 12/06/98 Drill 12 1/4" hole to 1 12/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2 12/13/98 Frac w/43000gls De	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gls 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gls 15% NEFE. etta & 75000# 16/30 sand.	ACOSPIC FEE	DAVID R GIASS 32 5 1993 BLM
subsurface locations and mer 12/06/98 Drill 12 1/4" hole to T 12/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2 12/13/98 Frac w/43000gls De 14. Thereby certify that the foregoing is true Signed	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE. etta & 75000# 16/30 sand.	o this zone.)*	Toposed work. If well is directionally drilled, give
subsurface locations and mea 12/06/98 Drill 12 1/4" hole to T 12/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2 12/13/98 Frac w/43000gls De 14. Thereby certify that the foregoing is true Signed Human II	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE. etta & 75000# 16/30 sand.	ACOSPIC FEE	DAVID R GIASS 32 5 1993 BLM
subsurface locations and mer 02/06/98 Drill 12 1/4" hole to T 02/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 02/12/98 Perf 28 holes from 2 02/13/98 Frac w/43000gls De 14. Thereby certify that the foregoing is true Signed	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE. etta & 75000# 16/30 sand.	ACOSPIC FEE	Dete
Subsurface locations and mer 12/06/98 Drill 12 1/4" hole to T 12/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 12/12/98 Perf 28 holes from 2 12/12/98 Perf 28 holes from 2 12/13/98 Frac w/43000gls De 14. Thereby certify that the foregoing is true Signed Signed Signed State of FICE USE) Approved By	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE. etta & 75000# 16/30 sand.	ACOSPIC FEE	DAVID R GIASS 32 5 1993 BLM
subsurface locations and mea 22/06/98 Drill 12 1/4" hole to T 22/07/98 Run & cmt 108 jts 5 02/11/98 Perf 3565'-3568' (4 Set cast iron bridge 22/12/98 Perf 28 holes from 2 22/13/98 Frac w/43000gls De 14. Thereby certify that the foregoing is true Signed March 1 Signed March 1 Shahara V. Hugh	asured and true vertical depths for all markers and zones pertinent i TD 4824'. 1/2" 17# J-55 csg. holes). Acidized w/1000gts 15% NEFE. plug @3521'. Tested to 5000psi. Held good. 2831'-3274'. Acidized w/3000gts 15% NEFE. etta & 75000# 16/30 sand.	ACOSPIC FEE	Dete

\*See Instruction on Reverse Side