| | | | | | C) S | |
|---|---|--|--|--|---|--|
| orm 3160-5 June 1990) | DEPARTMEN | ED STATES F OF THE INTERIOR AND MANAGEMENT | N.M. Oil Cons 811 S. 1st Stro | | res: March 31, 1993 | |
| | | ND REPORTS ON WE | to a different reservo | 821012834 | 75P Illottee or Tribe Name | |
| | SUBMIT | IN TRIPLICATE | | 7. If Unit or C | A, Agreement Designation | |
| I. Type of Well Oil Gas Well Well | Other | | | Robinson Ja 8. Well Name | | |
| 2. Name of Operator Vintage Drilling LLC | | | | RJU TR 2 # | | |
| 3. Address and Telephone N | 10. | | | 30-015-312 | 10 | |
| P.O. Box 158, Loco H 4. Location of Well (Foota | lills, NM 88255 50 ge, Sec., T. R. M. or Survey Desc | 5-746-1669 | | | Pool, or Exploratory Area ckson (Keely) | |
| | | , | | I 1. County or I | | |
| 1570' FNL 330' FEL | S-27, T-17S, R-29E | | | Eddy | | |
| | APPROPRIATE BOX(s |) TO INDICATE NATU | RE OF NOTICE, RE | | HER DATA | |
| TYPE OF : | SUBMISSION | | TYPE OF ACTI | ON | | |
| Notice of | of Intent | Abandonme | nt | Change | of Plans | |
| | ient Report | Recompletion | | | nstruction utine Fracturing | |
| | | Casing Rep | | Water S | hut-Off | |
| Final Abandonment Notice | | Altering Casing Other | | Convers | Conversion to Injection Dispose Water | |
| 13 Describe Proposed or Con | moleted Operations (Clearly state all | Destinent details and give pertinent of | | (Note: Report n Completion or | esults of multiple completion on Well Recompletion Report rind Log form) | |
| give subsurface loca 6/28/00 Spud Well 6/28/00 Set 348' 8 5/8" 2: 7/05/00 Set 3605' 5 1/2" 8/02/00 Perforate 3018' 8/03/00 Hot acid job w/3 8/04/00 Run 3435', 2 7/8" | mpleted Operations (Clearly state all ations and measured and true vertic 5# casing Circulate to surface, fell 17# casing, Circulate cement to su 3405', 29 shots, Acidize w/3000 g 15,000 gal 20% hot acid, alternatin " tubing, rods & pump. Hang well r zones after testing lower zone. | pertinent details, and give pertinent c al depths for all markers and zones p back 20 ft, ready mix to surface rface gal, 15% HCL g w/54,000 gal 40# water frac, foll | ates. including estimated date of bertinent to this work.)* | Lispose (Note: Report Completion or starting any proposed w | esults of multiple completion on Well Recompletion Report rind Log form) | |
| give subsurface loca 6/28/00 Spud Well 6/28/00 Set 348' 8 5/8" 2: 7/05/00 Set 3605' 5 1/2" 8/02/00 Perforate 3018'- 8/03/00 Hot acid job w/3 8/04/00 Run 3435', 2 7/8' Will complete upper | ations and measured and frue vertic 5# casing Circulate to surface, fell 17# casing, Circulate cement to su 3405', 29 shots, Acidize w/3000 g 5,000 gal 20% hot acid, alternatin, " tubing, rods & pump. Hang well r zones after testing lower zone. | pertinent details, and give pertinent c al depths for all markers and zones p back 20 ft, ready mix to surface rface gal, 15% HCL g w/54,000 gal 40# water frac, foll | ates. including estimated date of bertinent to this work.)* | EA | esuits of multiple completion on Well Recompletion Report rind Log form) vork. If well is directionally drilled | |
| give subsurface loca 6/28/00 Spud Well 6/28/00 Set 348' 8 5/8" 2: 7/05/00 Set 3605' 5 1/2" 8/02/00 Perforate 3018'- 8/03/00 Hot acid job w/3 8/04/00 Run 3435', 2 7/8' Will complete upper | ations and measured and frue vertic 5# casing Circulate to surface, fell 17# casing, Circulate cement to su 3405', 29 shots, Acidize w/3000 g 5,000 gal 20% hot acid, alternatin, " tubing, rods & pump. Hang well r zones after testing lower zone. | pertinent details, and give pertinent c al depths for all markers and zones p back 20 ft, ready mix to surface rrface gal, 15% HCL g w/54,000 gal 40# water frac, foll l on. | ates. including estimated date of bertinent to this work.)* | FA CURCE ARE CARE | esuits of multiple completion on Well Recompletion Report rind Log form) vork. If well is directionally drilled RECOMP 26 7 26 7 27 28 | |
| give subsurface loca 6/28/00 Spud Well 6/28/00 Set 348' 8 5/8" 2: 7/05/00 Set 3605' 5 1/2" 8/02/00 Perforate 3018'- 8/03/00 Hot acid job w/3 8/04/00 Run 3435', 2 7/8" | ations and measured and frue vertic 5# casing Circulate to surface, fell 17# casing, Circulate cement to su 3405', 29 shots, Acidize w/3000 g 5,000 gal 20% hot acid, alternating " tubing, rods & pump. Hang well r zones after testing lower zone. | pertinent details, and give pertinent c al depths for all markers and zones p back 20 ft, ready mix to surface rface gal, 15% HCL g w/54,000 gal 40# water frac, foll | ates. including estimated date of bertinent to this work.)* | FA CURCE ARE FA | esuits of multiple completion on Well Recompletion Report rind Log form) york. If well is directionally drilled NOT OT VED 20-P 2: 2 | |