Form 3160-5 (August 1999)

TITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

NM 14847

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUNDRY NOTICES AND REPORTS ON WELLS

abandoned well. Use Form 3160-3 (APD) for such proposals.					
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or N	
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator		30.0	* 2009 W	13	Federal Com #1
BOG RESOURCES, INC. 3a. Address P.O. Box 2267 Midland, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Sec. 7, T17S, R29E 2280' FNL & 1930' FWL	Description)	3b. Phone No. (include ar	ea AMPESIA	9. API Well No 10. 015-3147 10. Field and Po 11. County or F	76 ool, or Exploratory Area :h
12. CHECK APPROPRIATE	BOX(ES) TO IN	DICATE NATURE OF I	NOTICE, REPOR	RT, OR OTH	
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injecti		Production (S Reclamation Recomplete X Temporarily A Water Dispos	L L Abandon - al	Water Shut-Off Well Integrity Other
3. Describe Proposed or Completed Operation (clearly	y state all pertinent deta	ils, including estimated starti	ng date of any propo	sed work and a	pproximate duration thereo:

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

Procedure:

- Spot 150 gals 7% KCL Water w/ 1 gal/1000 Superflo III surfactant mixed w/ 150 gals methanol (total of 300 gals) across Morrow perforations from 10550-10400.
- 2. Set CIBP @ 10500' w/ 10' cement on top.
- 3. Set CIBP @ 10380' w/ 35' cement on top.
- 4. Load hole w/ 9.5# brine salt gel (25#/bbl) mud.

Note: This well will be temporarily abandoned upon the successful drilling and completion of the Warp Speed 7 Fed Com No. 2.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title				
Stan Wagner	Regulatory Analyst				
Star Wagner 300	Date 10/21/02				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by	Title Date ////8/62				
Conditions of approval, if any, are attached. Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.	t or Office CFC				