	_
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy Minerals and National Resources	Revised March 25, 1999
District I 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II	30-0 25=35024 -
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 2040 South Pacheco 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE
District IV Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Name:
PROPOSALS.)	Empire Deep "29" Federal
1. Type of Well:	Empire Deep 29 Federal
Oil Well Gas Well Other One of Operator	O. W. H.M.
2. Name of Operator Southwestern Energy Production Company	8. Well No. 1
3. Address of Operator	8. Pool name or Wildcat
2350 N. Sam Houston Parkway East, Suite 300 – Houston, TX 77032	Und. Morrow
4. Well Location	
Unit Letter : 550 feet from the N line and 370 fe	et from theW_line
Continue 20 T. 11 170 D. 20D) D (D) (D) (
Section 29 Township 17S Range 29E 10. Elevation (Show whether DR, RKB, RT, GR, e	NMPM Eddy County
3,626 GR	<i>IC.)</i>
11. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOI	
The same and the s	ALIZININO GAGINO EL
TEMPORARILY ABANDON	RILLING OPNS. PLUG AND
PULL OR ALTER CASING	ABANDONMENT
	AND
COMPLETION CEMENT JOB	
COMPLETION CEMENT JOB	_
OTHER: OTHER: Comp	
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	give pertinent dates, including estimated date
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	give pertinent dates, including estimated date
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation.	give pertinent dates, including estimated date
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	give pertinent dates, including estimated date
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324
OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimulate w/ 60 tons CO2 and 72 bb jts 2 3/8" tbg to 10,627'. Test well. Rel rig. Put on production 9/25/01.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324
OTHER: OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324
OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimulate w/ 60 tons CO2 and 72 bb jts 2 3/8" tbg to 10,627'. Test well. Rel rig. Put on production 9/25/01. I hereby certify that the information above is true and complete to the best of my knowledge.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324
OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb jts 2 3/8" tbg to 10,627'. Test well. Rel rig. Put on production 9/25/01. 1 hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE Production Analy	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324 RECLARIES OCD - ARTES dge and belief.
OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimulate w/ 60 tons CO2 and 72 bb jts 2 3/8" tbg to 10,627'. Test well. Rel rig. Put on production 9/25/01. I hereby certify that the information above is true and complete to the best of my knowledges and the structure of the start of the structure of the start of the	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324
OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimutate w/ 60 tons CO2 and 72 bb jts 2 3/8" tbg to 10,627'. Test well. Rel rig. Put on production 9/25/01. I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Title Production Analy Type or print varie Vonnie J Cermin/ (This space for State use)	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324 RECLARIES OCD - ARTES dge and belief.
OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimutate w/ 60 tons CO2 and 72 bb jts 2 3/8" tbg to 10,627'. Test well. Rel rig. Put on production 9/25/01. I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE Title Production Analy Type or print varie Vonnie J Cermin/ (This space for State use)	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324 RECLARIES OCD - ARTES dge and belief.
OTHER: Comp 12. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta or recompilation. 6/7/00 thru 6/10/00 MI RU CU. Log. Perf from 10,620-10,693. Swab. Stimplate w/ 60 tons CO2 and 72 bb jts 2 3/8" tbg to 10,627'. Test well. Rel rig. Put on production 9/25/01. I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE TITLE Production Analy Type or print parpe. Vonnie J Cermin/ (This space for State use)	give pertinent dates, including estimated date ch wellbore diagram of proposed completion ols Methanol. Set packer @ 10,583'. Run 324 RECLARIES OCD - ARTES dge and belief. rest DATE 9/27/01 Telephone No. 281-618-4739