

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 4 1972

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. |
| 7. Unit Agreement Name |
| 8. Farm or Lease Name Torres |
| 9. Well No. 1 |
| 10. Field and Pool, or Wildcat |
| 12. County Eddy |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| |
|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> |
| 2. Name of Operator John A. Yates |
| 3. Address of Operator Yates Building, 207 S. 4th St., Artesia, N.M. 88210 |
| 4. Location of Well UNIT LETTER <u>P</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>9</u> TOWNSHIP <u>18 South</u> RANGE <u>26 East</u> N.M.P.M. |
| 15. Elevation (Show whether DF, RT, GR, etc.) |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to pull tubing and rods and abandon by filling hole with heavy mud. Spot 25 sack cement plug at bottom of hole. Spot 25 sack cement plug at 1150' and set regulation marker in 10 sack cement plug at surface. Clean location.

Witness plugging - 5-24-72, 25/5X 1610 to 1485
25/5X 1150 to 1025 16/5X at surface OK. Marker - OK
Cemented by Denton Cementing Co used Increte, 14.0"
By S.A. Mermis

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rob Barber TITLE Bookkeeper DATE 8-3-72

APPROVED BY W.A. Gressitt TITLE OIL AND GAS INSPECTOR DATE AUG 4 1972

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness