

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-00192-0001

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
RC Resources, Inc.

3. Address of Operator
PO Box 1118, Cardiff, CA, 92007

4. Well Location
Unit Letter **H** : **1650** Feet From The **North** Line and **990** Feet From The **East** Line
Section **13** Township **18S** Range **26E** NMMPM **Eddy** County

7. Lease Name or Unit Agreement Name
Jones D

8. Well No. **1E**

9. Pool name or Wildcat
Atoka San Andres

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3300

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- ① PDH w/ Rods + Pump
- ② NU BOP and PDH with 2 3/8" tubing
- ③ Set bridge plug at 1654' above lower San Andres perms.
- ④ Pressure test bridge plug with 500 psig
- ⑤ Perf. 1556', 1560', 1564', 1570', 1574', 1579', 1581', 1585', 1590', 1594', 1597', 1605', 1610', 1614', 1618', 1625', 1630', 1636' and 1639' (upper San Andres)
- ⑥ T1H with test packer, spot acid, 1639'-1650', set packer @ 1530'
- ⑦ Acidize perms. 1556'-1639' with 1500 gal. acid
- ⑧ Swab test, evaluate if frac treatment required
- ⑨ If required, frac test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bolbi Duley TITLE Production Analyst DATE 11/31/00

TYPE OR PRINT NAME Bolbi Duley (760) 753-3330 TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

- ⑩ Run 2 3/8" tubing, rods, pump and resume normal production operations