

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

NEW MEXICO CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED
MAR 16 1971

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name Atoka Grayburg Unit
2. Name of Operator Kewanee Oil Company	8. Farm or Lease Name Tract 4
3. Address of Operator P. O. Box 3786, Odessa, Texas 79760	9. Well No. 3
4. Location of Well UNIT LETTER I , 2280 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 18S RANGE 26E NMPM.	10. Field and Pool, or Wildcat Atoka Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3306' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cement retainer at 850'. Squeezed open hole below retainer with 50 sacks at 1500 psi. Spot 100' cement plug 850' to 750'. Load hole with mud. Spot 100' cement plug 550' to 450'. Spot 100' cement plug 100' to surface. Weld plate on 7" casing and erect dry hole marker. Work completed March 13, 1971.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *E. F. Stinson* TITLE Division Superintendent DATE 3-15-71
APPROVED BY *P. L. Hume* TITLE OIL AND GAS INSPECTOR DATE JUN 11 1971
CONDITIONS OF APPROVAL, IF ANY: