Subnut 3 Copies to Appropriate	propriate ct Office gy, Minerals and Natural Resources Department RICT I Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088 RICT II Santa Fe, New Mexico 87504-2088		Form C-103 Revised 1-1-89 C
District Office <u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240			WELL API NO.
<u>DISTRICT II</u> P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Na			
DIFFERENT RESEF (FORM C	OPOSALS TO DRILL OR TO DEE RVOIR. USE "APPLICATION FOR -101) FOR SUCH PROPOSALS.)	PER OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL OAS WELL OAS	other SWD		Dayton Townsite Com (SWD)
Name of Operator YATES PETROLEUM CORPORATION		8. Well No.	
A Address of Operator 9		9. Pool name or Wildcat	
105 South 4th St., Art	esia, NM 88210	La Constanting	Dayton
4. Well Location Unit Letter: 165 SWNE Section 21	C Feet From The <u>185</u>	Range 26E	<u>BID</u> Feet From The <u>East</u> Line NMPM Eddy <u>County</u>
	10. Elevation (Show whe	ther DF, RKB, RT, GR, etc.)	
	Appropriate Box to Indica	ta Natura of Notice E	
			SEQUENT REPORT OF:
	F	_	
	PLUG AND ABANDON		
	CHANGE PLANS		
PULL OR ALTER CASING		CASING TEST AND C	
		OTHER: Acidize	injection interval K
	ations (Clearly state all pertinent deta	ils, and give pertinent dates, incl	uding estimated date of starting any proposed
down tubing. Release and 400' of 2-7/8" up TOOH. Laid down bail 1-11-95 - TIH with 5- coated tubing to 8810 Loaded with 38 more b with nickle plated tu Pumped 500 gallons xy 1-12-95 - Acidized in	ed packer and nipple oset tubing and plas ler and tubing. Shu -1/2" 14-17# Baker L)'. Pumped 140 bbls obls. Pressured ann ubing hanger. Press ylene down tubing.	d up BOP. TOOH. tic coated tubing t well in. ok-Set nickel pla packer fluid dow ulus to 500 psi. ured annulus to 4 Flush to end of p s 8902-9162' w/10	own injection line. Pumped TIH with bulldog bailer . Cleaned out from 9020-9090'. ted packer on 2-7/8" plastic n annulus. Set packer. Nippled down BOP. Flanged up 00 psi for 30 minutes, OK. acker. Shut well in. 000 gallons 15% NEFE gelled
agid with 1000# rock	salt as follows: 5	000 gallons acid,	flushed with 50 bbls KCL,
acid with 1000# rock 1000 gallons gelled b to production.	salt as follows: 5 prine with 1000# roc	000 gallons acid, k salt and 5000 g	flushed with 50 bbls KCL, allons acid. Released well
acid with 1000# rock 1000 gallons gelled b	salt as follows: 5 prine with 1000# roc	000 gallons acid, k salt and 5000 g ge md belief.	flushed with 50 bbis KCL, allons acid. Released well
acid with 1000# rock 1000 gallons gelled b to production.	salt as follows: 5 prine with 1000# roc we and complete to the best of my knowled	000 gallons acid, k salt and 5000 g ge md belief.	flushed with 50 bbis KCL, allons acid. Released well
acid with 1000# rock 1000 gallons gelled b to production. I hereby certify that the information above is bu SKONATURE	salt as follows: 5 prine with 1000# roc we and complete to the best of my knowled	000 gallons acid, k salt and 5000 g ge md belief.	Clerk DATE 1-12-95