

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION RECEIVED BY  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87801  
OCT 8 1985  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. Name of Operator  
Yates Petroleum Corporation  
3. Address of Operator  
207 South 4th St., Artesia, NM 88210  
4. Location of Well  
UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM  
THE East LINE, SECTION 22 TOWNSHIP 18S RANGE 26E NMPM.

7. Unit Agreement Name  
8. Farm or Lease Name  
Flint GU  
9. Well No.  
4  
10. Field and Pool, or wildcat  
Undesignated  
12. County  
Eddy

15. Elevation (Show whether DF, RT, GR, etc.)  
3336' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Set CIBP, Perforate, Treat <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-4-85. WIH and perforated 6249-6318' w/16 .50" holes as follows: 6249, 50, 51, 52, 53, 54, 55, 70, 71, 72, 73, 74, 6315, 16, 17 and 18'.  
9-6-85. Set CIBP at 6400' w/35' cement on top. Spotted acid across perfs 6249-6318' (16 shots). Set packer and flanged up. Acidized zone w/2000 gals 15% NEFE acid + 2% KCL.  
9-10-85. Re-acidized zone 6249-6318' w/10000 gals 15% NEFE gelled Retarded acid + CO2.  
POOH w/packer.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Guaranta Goodlett TITLE Production Supervisor DATE 10-7-85  
Original Signed By Mike Williams TITLE Oil & Gas Inspector DATE OCT 15 1985  
APPROVED BY Mike Williams  
CONDITIONS OF APPROVAL, IF ANY