

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

MAR 15 1972

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Mayer Holt
9. Well No. 1
10. Field and Pool, or Wildcat Atoka Penn. Gas
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-
2. Name of Operator Mallard Exploration, Inc.
3. Address of Operator 1306 V & J Tower, Midland, Texas 79701
4. Location of Well UNIT LETTER <i>K L</i> 990 FEET FROM THE West LINE AND 1650 FEET FROM THE South LINE, SECTION 28 TOWNSHIP 18S RANGE 26 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3413 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. This form is filed as Notice of Intention to Plug and Abandon according to the following:

- 1) Circ. hole with mud laden (25 sx/100 bbl.) fluid. Pull tubing. Set bridge plug
- 2) Set cast iron bridge plug with 2 sx. cement at 9000'. at 1514 would not go to 9,000
- 3) off 4 1/2" casing and recover approximately 8000'. Shot off 7650 would not come
- 4) Set 35 sx. cement plugs at the following depths:
 - * a. 8000' on stub 7 1/2"
 - b. 5050' 5950
 - c. 4500'
 - d. 2300'
 - e. 1325'
 - f. 875'
 - g. 10 sx. at the surface.

5) Marker

Note: 4-1-72 casing placed at 4500' had to come all the way out of hole with 4 1/2" casing and pick up tubing & set rest of plugs.

Estimated date work will begin - March 25, 1972.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wayne A. Munro TITLE Production Superintendent DATE March 13, 1972

APPROVED BY W.A. Grasset TITLE _____ DATE 3-15-72

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness Plugging operations.