

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-00256
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	004378
7. Lease Name or Unit Agreement Name	Ralph Nix
8. Well No.	1
9. Pool name or Wildcat	Atoka (Penn)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Chi Operating, Inc.	8. Well No. 1
3. Address of Operator 212 North Main; Midland, TX 79701	9. Pool name or Wildcat Atoka (Penn)	
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 29 Township 18S Range 26E NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) G.L. = 3416	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

01-27-98 - MIRU.

01-28-98 - Notified OCD. Unable to recover production packer. Pumped 30 sx C cmt on top of packer @ 8906', no tag. POOH w/ tbq.

01-29-98 - Set 7" CIBP @ 8453', tagged. Circulated mud and pumped 20 sx C cmt 8453-8332'. RIH w/ 7" CIBP and set @ 6300', tagged. Circulated hole w/ mud.

01-30-98 - Notified OCD. Continued circulating hole. Pumped 20 sx C cmt 6300-6180'.

02-02-98 - Contacted Ken Livingston w/ OCD. RIH w/ CBL tool, TOC @ 510'. Loaded hole w/ mud and pumped 25 sx 4030-3880'. Ppumped 25 sx C cmt 2393-2243'. Pumped 25 sx C cmt w/ CaCl₂ @ 1574'. WOC and tagged @ 1445'. Pumped 15 sx C cmt 40'-surface. RDMO.

02-06-98 - Cut off wellhead, capped well, installed dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John W. Wolf TITLE Engineer DATE 2/6/98
TYPE OR PRINT NAME JOHN W. WOLF TELEPHONE NO. 915-685-5001

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: