## July 17, 1961

Mr. E. P. Campbell 1603 Broadway Lubbock, Texas

> Re: Dorothy Sanford et al Well # 1, Unit J, Sec. 34-185-26E, Eddy, N. M.

Dear Sir:

A recent inspection of the site of the above-captioned well showed that the pits have not been filled as yet. Also, we need three (3) copies Form C-103, (Plugging Report) on this well.

Please get the pits filled and the Plugging Report in to this office as soon as possible.

Very truly yours,

OIL CONSERVATION COMMISSION

MLA/sa

M. L. Armstrong Supervisor, District No. 2 139 8 NE 2606

air, J., F., Carpberl, 1603 Broadwey Habbook, Taxes

1

Re: Dorothy Sanford et al Rell / 1, Criter, Sec. 34-189-285, 2008/, 2011

TTLO SOU

A recent inspection of the alte of the above-continned well showed that the pite have not been filled as yet. Also, we need three (3) contes form 5- 33, (Plassing Report) on this well.

liasse get the pite filled and the "lugging report in to this office as soon as possible.

, study almat they

REALEND REFLECTION RECT

Me . A.L

1. L. Andekrong Supervisor, Matrict So. 2