30-015-00279 Munday Induction Log •



## OIL CONSERVATION COMMISSION

207 CARPER BUILDING

ARTESIA, NEW MEXICO

December 21, 1959

Standard Oil Co of Texas P. O. Box 698 Monchans, Texas

> Re: Paul Terry et al Well #1, Unit F, Sec 15, T18S, R26E

Attention Mr. C. F. Dwyer

Gentlemen:

A recent field inspection of the location of the subject well reveals that the cellar is not filled, there is a swedge on the 10 3/4" inch casing and the well is leaking a small amount of gas. It is necessary that the cellar be filled, the gas shutoff and a standard marker showing the location of the well be set in the hole before the plugging of this well can be approved.

Please notify this office on form C-103 when this work has been completed.

Yours very truly,

OIL CONSERVATION COMMISSION

M. L. Armstrong, Supervisor, District No. 2

MLA/jn