

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

DO NOT SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Expires August 31, 1985

CSF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

AUG 7 10 53 AM '87

CARLSBAD RESOURCE
AREA HEADQUARTERS

RECEIVED BY
AUG 13 1987
C. C. D.
ARTESIA, OFFICE

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
ARCO Oil and Gas Company ✓

3. ADDRESS OF OPERATOR
P. O. Box 1610, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with all State requirements.
See also space 17 below.)
At surface 1980 FSL & 1980 FEL (Unit Letter J)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3643 DF

5. LEASE DESIGNATION AND SERIAL NO.
NM 016788

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Empire Abo Unit "K"

9. WELL NO.

19

10. FIELD AND POOL OR WILDCAT

Empire Abo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

1-18S-27E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☒

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6-25-87 RUPU. Kill well w/40 BO. POH w/pkr. WL set RBP at 6036. Run CBL.
Indic TOC at 5170. Perf at 5166. RIH w/pkr. Est circ out 4-1/2 x 8-5/8

6-29-87 Set CR at 4744. Sqz w/1570 sx "C" & displace cmt below tool. Did not
circ cmt.

6-30-87 TOH w/CR. Ran Free Pipe log. TOC at 2013. Perf at 1950. Set CR at 1507.
Sqz w/565 sx "C". Circ cmt to surf.

7-1-87 Drill out cmt to 1955. Press test to 630#.

7-2-87 Drill out to 5220. Press test to 580#. POH w/RBP. RIH w/CA. Set pkr at
6094. Press test to 600#. Return to prod. 7-6-87.

ACCEPTED FOR RECORD

SJS

AUG 10 1987

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Ken W. Gosnell

TITLE

915-688-5672

Engr. Tech. Spec.

DATE

8-4-87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side