Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

LES BABYAK
PETROLEUM CNOINEER

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS						5. Lease Serial No. NM-016788				
	Do not use th abandoned we	is form for proposals to all. Use Form 3160-3 (AF	o dril PD) fo	l or to re-enter r such proposal	an s.		6. If Ind	ian, All	ottee or Tribe Name	
	SUBMIT IN TR	IPLICATE - Other inst	ructi	ons on reverse	side)	7. If Un	it or CA	/Agreement, Name and/or	No.
					678		Emp	oire	Abo Unit	
	Type of Well	n /		/23"		174 ₀	8. Well	Name a	and No.	
	Name of Operator	Other		-// -	<u>T</u>	10 6	Emr	oire	Abo Unit K-2	20
2.	B-P America Prod	uction Co.		31		XVX E	9. API	Well No).	
3a.	Address		3	b. Phone No. (include			-		-00697	
	P.O. Box 1089.	Eunice, N.M. 882	31	5052677-3	642	RTESIA	1 /		ol, or Exploratory Area Abo	
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description)								arish, State	
	Unit Letter I,		FE	L \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		مرور الم		-		
	Sec. 1, T18S,	R27E		£36	350	2221	Edd	dy,	New Mexico	
	12. CHECK AP	PROPRIATE BOX(ES)	TOIN	IDICATE NATU	RE O	F NOTICE, R	EPORT,	OR O	THER DATA	
	TYPE OF SUBMISSION					F ACTION				
	THE OF SUBMISSION	D		Deepen		Production (Star	rt/Resume)		Water Shut-Off	
X	Notice of Intent	Acidize Alter Casing		Fracture Treat		Reclamation	o Rosanio)		Well Integrity	
_		Casing Repair	_	New Construction		Recomplete			- -	
L	Subsequent Report	Change Plans	$\bar{\mathbf{x}}$			Temporarily Al	bandon			
	Final Abandonment Notice	Convert to Injection		•		Water Disposal				
	Procedure to P&A (1) MIRU, ND WH, (2) Release pkr. (3) RIH w/tbg. w (4) TIH w/CIBP & (5) Circ. & test (6) Circ. hole w (7) Cap CIBP @ 5 (8) TIH w/pkr. & 3039'. WOC	Rorfinal inspection.) 83' Perfs 5956' 1: NU BOP & Environ 1: POH w/tbg. & 1: A POH w/	-61 pkr Jash ne nud. cmt.	22', 6159' t @ 2294'. 2 sxs. sar water.	-617 ad of	75'. Hold	es in (csg.	@ 2977' to 30	
14.	I hereby certify that the forego	ing is true and correct					10		1	
_	Signature M. Ment	Whitmine		Title (P	erationas 11-26-	() 02	eas	list	
	2 (THIS SPACE	E FOI	R FEDERAL OR	STAT	E OFFICE US	E			
۸-	proved by	THO.			Title	Γ	۸۲	DIE	POVED	
Co	onditions of approval, if any, are tify that the applicant holds leg tich would entitle the applicant	galfor equitable title to those r	otice d ights in	oes not warrant or n the subject lease	Office				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
	tle 18 U.S.C. Section 1001 and Toles and false fictitions of transfer		ake it	a crime for any person	n know	ringly and willful	ly to make	d any d	epartment of agency of the	e United

PLUGGING & ABANDONMENT WORKSHEET (2 STRING CSNG) BP America Production 6 **OPERATOR** LEASENAME EAU WELL Part 42 csg 0 K-20 Unit Ltv. I 60' ciac. 155x cm + tosurface 185 RNG 278 TWN SECT 660 E/W L M/S L FROM FORMATION @ TD TD: **FORMATION @ PBTD** PBTD: Perf 4/2 < 562 1572 1 592 50 sxrcm+ TOC SET @ TOC DETERMINED BY SIZE 850 85/2 -24# SURFACE Surface 1522 CiRC. 850545 INTMED 1 @ 1522 INTMED 2 TOC surface 4/2 9.5 # 6185 5500 2005xs-calculate PROD TOP BOT TOC DETERMINED BY soltgel SIZE mud LINER 1 592 holes 2817 6 LINER 2 3039 W/355xcm+ TOP - BOTTOM **CUT & PULL @** 5956-6034 INTMED 1 PERFS INTMED 2 PRIFES 6159-6175 cincholow 9.5th Perfs sait Gelmud CIBPE 5906 cappe PROD 5956-*REQUIRED PLUGS DISTRICT I w/251xcm+. 6122 PLUG SACKS DEPTH 42 9.5世 TYPE RUSTLER (ANHYD) 418P0 PLUG CMNT @6185 YATES 6146 EXAMPLES TOC 5500 QUEEN OH 35 SXS 6400' PLUG#1 ORAYBURG SHOE 50 SYS 5350'-5450' PLUO # 2 CAN ANDRES CIBP/35' 4800 PLUG#3 CIBP4800" PLUO#3 25 SX'S CAPITAN REEF 3600'-3700' 50 SXS STUB PLUG#4 200 SXS 400 RETNR SQZ 12LUG#5 OELAWARE 10 SXS 0-10' SURF PLUG#6 BELL CANYON PAH'd Well 6146 CR CHERRY CANYON PLUG#I CTBP 5906 25 sx BRUSHY CANYON 592 40 b PLUG#3 3554 3039-2877 DONE EPRING PLUG#4 1572 - 1472 505 60-0 Sur face PLUG#5 **OLORIETA** PLUG#6 BLINEBRY LUGST LUEB MUOSE DRINKARD MLXX)#9 ADO PLUG# 10 PLUG# wc PLUG# PENN STRAWN ATOKA MORROW DEVONIAN

Empire Abo Unit 'K' 20

Potential Perforation Zones

