

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Submit in triplicate
(Other instructions on reverse side)

Expires August 31, 1984

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

ARCO OIL AND GAS COMPANY

3. ADDRESS OF OPERATOR

BOX 1710, HOBBS, NEW MEXICO 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below)
At surface

959.04

-995.04 FSL - 1644.42 FWL (UNIT LETTER N)

14. PERMIT NO.

30-015-00713

15. ELEVATIONS (Show whether DP, RT, CR, etc.)

3621 RKB

RECEIVED

MAY 19 1992

O. C. D.
OFFICE OF THE COMMISSIONER

5. LEASE DESIGNATION AND SERIAL NO.

8910138010

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

EMPIRE ABO UNIT "L"

9. WELL NO.

18

10. FIELD AND POOL, OR WILDCAT

EMPIRE ABO

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

SEC. 1, T18S, R27E

12. COUNTY OR PARISH 13. STATE

EDDY

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREATMENT ☐

MULTIPLE COMPLETION ☐

SHOOTING OR ACIDIZING ☐

ABANDON* ☐

REPAIR Casing ☐

CHANGE PLANT ☐

(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

(Other) TEMPORARILY ABANDON ☒

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE WORK DONE OR COMPLETED OPERATIONS. Fully state all pertinent details, and give pertinent dates, including estimated date of starting any work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones penetrated by work.

HOLD WELL BORE AS A MONITOR WELL (BHP SURVEY)

TD 6174'; PBD 6080'; PERFS: 6042-56'; CIBP 5954'

5/5/91 RIH w/PKR, SN & TBG. TAG CIBP, POH w/1 JT, SET PKR. PUMPED 35 BBLs 8.6# BRINE w/WT-675 CHEMICAL DOWN TBG, WOULD NOT PRESSURE UP. RU KILL TRUCK ON CSG. LOAD & PRESSURE CSG TO 500#. HELD GOOD. HAD TROUBLE RELEASING PKR.

5/6/92 POH LEFT PACK OFF RUBBER & CONE OF PKR IN HOLE. RIH w/PKR, SN & TBG. RU KILL TRUCK PUMP 50 BBL 8.6# BRINE w/WT-675 CHEMICAL BY PKR. ND WH SET PKR w/13000# COMPRESSION, LOAD & PRESSURE CSG TO 550#. HELD FOR 30 MIN. PKR SET @ 5929.79'. TEST WITNESSED BY GARY WILLIAMS-NMOC. CHART ATTACHED w/ NOTE BY GARY WILLIAMS-NMOC.

APPROVED FOR 12-MONTH PERIOD

ENDING 06-01-93

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Coordinator

DATE 5/13/92

(This space for Federal or State use only)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

