

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-00733
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-7244
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "J"
8. Well No. 13
9. Pool name or Wildcat EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER
2. Name of Operator BP America Production Company
3. Address of Operator P.O. Box 1089, Eunice, NM 88231
4. Well Location Unit Letter E : 660 Feet From The W Line and 1980 Feet From The N Line Section 2 Township 18S Range 27E NMPM EDDY County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3581' RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Workover ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6131' PBD: 6090' PERFS: 5688-5723, 5754-5784' (old), 5382-5658' (new)

06.21.02: MIRUPU. NDWH. NUBOP. POH w/tbg. SN, SV, & pkr.
06.24.02: RIH w/tbg. Hot oil tbg. POH w/tbg.
06.25.02: RIH w/bit, scraper, & tbg. Tested tbg in hole. Tag @ 5970'.
06.26.02: Perf 2 JSPF, 5382-86', 5390-98', 5454-60', 5482-88', 5514-38', 5589'
5610-16', 5642-58'. RIH w/RBP, pkr, SN & SV. Set plug @ 5666'.
06.27.02: Set pkr @ 5290'. Pmp 500 gals 7.5% HCL NEFE acid & 3 BW. Swab back
acid. Pmp 3650 gals 15% HCL NEFE acid w/200 ball sealers. Unset pkr.
RIH & unset RBP. POH.
06.28.02: NDWH. NUBH. Swab well. Return well to production 07.01.02. In 24
hrs pmp 0 bo, .1 bw, 366 mcf.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 08.01.02
TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505.394.1649

(This space for State Use)

AUG 8 2002

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL: Accepted for record - NMOC