

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 80, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-00740

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.
B6869

7. Lease Name or Unit Agreement Name

South Redlake Grayburg

8. Well No.

40

9. Pool name or Wildcat

Red Lake Q-G-SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER Injection

2. Name of Operator

McQuadrangle, L.C.

3. Address of Operator

7008 Salem, Lubbock, TX 79424

4. Well Location

Unit Letter G : 1650 Feet From The North Line and 2197 Feet From The East Line

Section 2 Township 18S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/01/02 Spot 25 sx "C" cmt. @ 1608', WOC & tag TOC @ 1292'.

7/02/02 Circulate hole w/ mud.

7/02/02 Cut off and pull 4-1/2" csg. from 260', spot 25 sx cmt. w/ 3% CaCl, WOC & tag plug @ 237'. Plug spotted @ 315'.

7/02/02 Re-spot 25 sx cmt. WOC until next day.

7/03/02 Tag cmt. plug @ 200', spot 20 sx w/ 2% CaCl @ 200', WOC (did not tag). Re-spot 30 sx cmt. w/ 2% CaCl, WOC & tag plug @ 150'. Spot 20 sx cmt. w/ 2% CaCl, WOC & tag plug @ 147'. Spot 20 sx, WOC until next day.

7/08/02 RIH to tag plug (did not tag) load up hole (csg. went on vac.). Spot 10 sx cmt. w/ 2% CaCl, WOC & tag plug @ 120'. Re-spot 30 sx WOC (did not tag).

7/09/02 Mix 3 sx Maxi Seal (L.C.M.) let it set 30 min. load up hole (went on vac.) Mix 3 more sx (L.C.M.), spot 20 sx cmt. w/ 2% CaCl, WOC & tag plug @ 37'.

7/10/02 Cut csg. @ 31', spot 30 sx to surf. RDMO. Install dry hole marker, clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Roger Massey

TITLE Agent

DATE 7-19-02

TYPE OR PRINT NAME

Roger Massey

TELEPHONE NO. (915) 530-0907

(This space for State Use)

APPROVED BY

[Signature]

TITLE

[Signature]

DATE

OCT 22 2002

CONDITIONS OF APPROVAL, IF ANY: