Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

PORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS		LC061783A
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		6. If Indian, Allottee or Tribe Name
	PERMIT - " for such proposals	
		7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE		8910138010
1. Type of Well		
X Oil Gas Well Other		8. Well Name and No.
2. Name of Operator ARCO Permian	RECLIVEL	EMPIRE ABO UNIT K-8 9. API Well No.
3. Address and Telephone No.		30-015-00774
P.O. Box 1710 Hobbs, N.M. 88240	505-391-1648ANV 1 7 1996	10. Field and Pool, or exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey De		EMPIRE ABO
1650' FSL & 330' FEL, UNIT LETTER I- Lot 13 SEC. 4, T18S, R27E OIL CON. DIV.		11. County or Parish, State
550. 4, 1100, 1272	OIL COLOR	EDDY NM
GUEGE ADDROLL TO DOLLAR	DIST. 2	I
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPORT	, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
 1	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
\Box	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other DRILL OUT CIBI'/PERF	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drille give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		
TD: 5602' PBD: 5566' PERFS: 5400-5474', 5502-5552'		
03/27/96: RIH W/3-7/8" BIT, 6-DC, & TBG. DRILL OUT CIBP @ 5300'. SET PKR @ 5450'.		
03/28/96: ACIDIZE ABO PERFS 5502-5552' W/2000 GALS 50/50 ACID/CONDENSATE RUNNING 100 BALL		
SEALERS. SAW VERY LITTLE BALL ACTION. MAX PRESS 150#, MIN PRESS VAC, AVG PRESS 75#. AIR 2.5 BPM.		
03/29/96: ATTEMPT TO SPOT ACID WOULD NOT CIRC. POH SET PKR @ 5354'. ACID ZE ABO PERFS 5400-5474' W/2500 GALS 15% NEFE ACID. MAX PRESS 120f, MIN PRESS VAC, AVG PRESS 60f. AIR 2.6		
BPM.		
04/03/96: RU WIRELINE RUN CBL 5552' TO 4900'. POOR BONDING IN INTERVAL OF NEW PERFS. SUSPECT WATER PRODUCTION FROM BEHIND PIPE F/LOWER PERFS TO NEW PERFS IN UPPER ABO. RIH W/W/C		
SET CIBP. SET CIBP @ 5380'.		
04/04/96: CIRC 90 BBLS 8.6# BRINE W/TH-377 CHEM. CLOSE IN BOP PRESS UP TO 600#, HELD FOR 30 MINS. PRESS TEST CHART ATTACHED. AWAIT EVAL OF OFFSET WELLS. WELL IS: TA'D W/CIBP SET @		
ACCEPTED SOR RE		
AUGENERAL SEE		
H		
MAY 13 E13		
, CARLSBAD, NEW ME	EXICO	
14. I hereby certify that the foregoing is true and correct		
Signed Fresher H. Musse	Title Administrative Assistant	Date 04/12/96
(This space for Federal or State office use)		
Approved by	Title	
Conditions of approval, if any:	1105	Date