

RECEIVED

60-5
89)

JUL 24 1991

UNITED STATES
DEPARTMENT OF THE INTERIOR

O. C. D. BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NM60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
LC-049648 (A) **BS**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Julia "A" Federal

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Red Lake Queen Grayburg

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 5, T-18S, R-27E **BS**

12. COUNTY OR PARISH
Eddy

13. STATE
NM

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)
Unknown

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANT

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☒
☐

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Completed Operations:

7/09/91: MIRU Ice Well Service. POOH w/ 75-3/4" rods & pmp. POOH w/ 58 jts 2-3/8" tbg. RIH w/ tbg to 1792'. Circ hole w/ FW. Pmp 20 sx cmt w/ 1 sx cellophane. POOH w/ 30 jts tbg. SDON.

7/10/91: Kathy Queen w/ BLM on loc. Tag TOC w/ WL @ 1540'. RIH w/ tbg & load hole w/ 9.5# mud. POOH w/ tbg to 1332'. Pmp 20 sx cmt. POOH w/ tbg. Shot csg @ 1050'. Set cmt ret on WL @ 950'. RIH w/ tbg & sting into cmt ret. Could not pmp into @ 1000#. Called Shannon Shaw w/ BLM for P&A procedures. POOH w/ tbg. RIH w/ 5-1/2" pkr & 2 jts tbg. Set pkr & tstd csg to 500#. Held ok. POOH w/ tbg & pkr. Shot csg @ 750'. RIH w/ pkr & tbg. Set pkr @ 550'. Estb circ out 5-1/2" annulus. Pmp 60 sx cmt. Disp cmt to 650'. Had good circ throughout sqz. SD 30 min. POOH w/ tbg & pkr. Shot csg @ 350'. RIH w/ pkr & 2 jts tbg. Pmp 140 sx cmt. Cmt circ. Rel pkr & POOH. Fill 5-1/2" w/ cmt to surf. SD 2 hrs. Cmt in annulus falling slightly. Pmp 15 sx cmt in annulus to surf w/ hose. SDON.

7/11/91: TOC 12" from surf. Dmp cmt to fill hole 2" from surf. RDMO.

7/12/91: Cleaned up location.

7/15/91: Constructed dry-hole marker.

Approved to leave well as is until bore.
Liability under bond is waived until
surface restoration is completed.

Post ID-2
8-2-91
P & A

18. I hereby certify that the foregoing is true and correct

SIGNED

Belinda Lawler
Belinda Lawler

TITLE Production Clerk

DATE 7-17-91

(This space for Federal or State use)

APPROVED BY

TITLE

DATE

7/23/91

CONDITIONS OF APPROVAL, IF ANY.