	NIMOCC 4	COPY		Copy to St
Form 9-331 (May 1963)	NMOCC		SUBMIT IN TRI ACATE	Form approved.
	DEPARTM	INT OF THE INTER	IOR (Other instructi, . on r	e-Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
		OLOGICAL SURVEY		
			C-026874 (e) 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
S	UNDRY NOTIC	ES AND REPORTS	ON WELLS	
(Do not use	Use "APPLICATI	to drill or to deepen or plug ON FOR PERMIT—" for such	back to a different reservoir. proposals.)	이 지원에 관망하는 것 공품이 있는 것
1.			······································	7. UNIT AGREEMENT NAME
OIL KX GAS			RECEIVI	ED
2. NAME OF OPERATO				8. FARM OR LEASE NAME
Petroloum	Corporation		JUN - 1 1978	
3. ADDRESS OF OPER	Corporation c	i Texas V	JUN - 1 1978	5 Eaton Federal
P. O. Box				
4. LOCATION OF WEL	L (Report location clean	enridge, TX 76024 rly and in accordance with an	State requirements, C. C.	10. FIELD AND POOL, OR WILDCAT
See also space 17 At surface	below.)	i, all in accordance with an	ARTESIA, OFFICI	
	2970	FEL		Red Lake Queen Grayburg S 11. SEC., T., B., M., OB BLK. AND
Unit K, 1650' FSL & 2330' FWL, S-5, T-18-S, R-27-E				SURVEY OR AREA
				5-18S-27E-NMPM
14. PERMIT NO.		15. ELEVATIONS (Show whether D	F RT CR etc.)	12. COUNTY OR PARISH 13. STATE
			,,,,	
		3487'		Eddy New Mexico
16.	Check Appr	opriate Box To Indicate I	Nature of Notice, Report, or	Other Data
	NOTICE OF INTENTIO			QUENT REPORT OF:
	[]	[]		
TEST WATER SH		L OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTUBE TREAT		TIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZ		NDON*	SHOOTING OR ACIDIZING	
REPAIR WELL		NGE PLANS	(Other)	ts of multiple completion on Well
(Other) Shut	off perfs @	1816'-1831' LXX	Completion or Recom	pletion Report and Log form.)
proposed work.	. Il wen is unectional	ly drilled, give subsurface loc	nt details, and give pertinent dates ations and measured and true verti-	s, including estimated date of starting any cal depths for all markers and zones perti-
nent to this wo:	(K.) •			하는 꽃 학원 것 이 물이 유지 승권이 있는 것이다.
C + 1				
Gentlemen:				· · · · · · · · · · · · · · · · · · ·
To chut off	rotor and			
to shut off	water product	ion, we submit th	e following procedure	
1. Set ret	miomobile levels	1 0 17(0)		/ · 프랑토철 · 문 생각하는 · · · · ·
I. SEL LEL	TIEVADIE Dridg	se plug @ 1760' to	shut off lower perf	@ 1816'- = 1831'.
2. Return				
z. Ketuin	well to produc	tion to test uppe	r perfs @ 1628' - 170) 1'- 중변출원은 중 위성물고
				· · · · · · · · · · · · · · · · · · ·
				물일학실용 물 관광 관광 동물
			0	FU
			K	
				HELLUN NEW MENT
				U.S. TSA
				토속날이며 국립·관이북동
18. I hereby certify 1	hat the foregoing is tri	ue and correct		
SIGNED	The man		vision Superintendent	
Art	hur Boice			NAIN_LIGY
(This space for H	Federal r State office u	se)		
APPROVED BY	De A.	LALL TITLE AL	CTING DISTRICT ENGINEE	RMAY 31-1978
CONDITIONS OF	APPROVAL, IF ANY	:		
				요즘 한 편의 것 및 문양 및 문
		***		이 왜 빠지 않는 도장 명

*See Instructions on Reverse Side

-