

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NMD60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.
LC-060894

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Paton Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Red Lake Queen Grayburg
San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 6, T-18S, R-27E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Breck Operating Corp.

3. ADDRESS OF OPERATOR

P.O. Box 911, Breckenridge, Texas 76024

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit Letter "F"; 1650' FNL & 2310' FWL

14. PERMIT NO.

DATED: 8/11/47

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3424' DF

O. C. D.

ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

COMPLETED OPERATIONS

8/14/90: MIRU. POOH w/ 74-5/8" rods and pmp. PU tbg to remove slips. Tbg parted in collar 10 jts down. RIH and screw into collar. POOH w/ 10 additional jts (20 jts total). Tbg very badly corroded. RIH w/ 7" pkr & 1 jt tbg. SDON. Received verbal permission from Shannon Shaw w/ BLM in Carlsbad, N.M. to set pkr @ 500' & pmp 150 sx cmt plug.

8/15/90: RIH w/ tbg & pkr to 470'. Loaded hole w/ 9.5 ppg mud. Set pkr & pmp 200 sx cmt. Displaced cmt to 550'. Press up to 250#. POOH w/ tbg & pkr. Perf @ 500'. RIH w/ tbg & pkr to 120'. Set pkr & pmp 100 sx cmt. Displaced to 400'. SD for 3 hrs. POOH w/ tbg & pkr. RIH w/ WL & tag TOC @ 415'. POOH. Perf @ 100'. RIH w/ 1 jt tbg & pkr. Set pkr & pmp 135 sx cmt. Circ cmt to surf. RDMO. BLM rep Cathy Queen witnessed P&A procedure.

8/16/90: Dumped surface plug. Cut off wellhead. Weld on plate. Const Dry-Hole marker. Well P&A.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Petroleum Engineer

DATE 8/20/90

(This space for Federal or State office use)

APPROVED BY Orig. Signed by Adam Salameh

TITLE PETROLEUM ENGINEER

DATE 8-28-90

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NM OIL CONG. COM. IN
Drawn by SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR Breck Operating Corp. ✓
3. ADDRESS OF OPERATOR P.O. Box 911, Breckenridge, Texas 76024
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
Unit Letter "F"; 1650' FNL & 2310' FWL

13. PERMIT NO. DATED: 8/11/47
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3424' DF

5. LEASE DESIGNATION AND SERIAL NO.
LC-060894

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Paton Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT
Red Lake Queen Grayburg
San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 6, T-18S, R-27E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐
FULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. GEOPHYSICAL PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

WELLBORE DATA:

Production Casing: 7" set @ 1444' w/50 sx. cmt.

Completion Interval: 1470'-75' (OH)

1550'-54' (OH)

1820'-35' (OH)

TD: 1982'

PBTD: 1940'

PROPOSED OPERATIONS*

1. Set CIBP @ 1400' & dump 7 sx. cmt. on top from 1400'-1365'.
2. Perforate 7" csg. @ 500' & squeeze 50 sx. cmt. from 500'-450' inside & out. Tag TOC.
3. Perforate 7" csg. @ 100' & circ. cmt. to surface inside & out. Should take 85 sx. cmt.
4. Cap well and construct dry hole marker.

NOTE: Hole will be loaded with 9.5 ppg mud.

* Proposed operations recommended by Shannon Shaw of BLM in Carlsbad, NM.

18. I hereby certify that the foregoing is true and correct

SIGNED Shannon Shaw

TITLE Petroleum Engineer

DATE 11/09/89

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

PETROLEUM ENGINEER

TITLE

DATE

11-16-89

* NOTIFY BLM - - -

*See Instructions on Reverse Side