

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	3001500809
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	West Red Lake
8. Well No.	3
9. Pool name or Wildcat	Red Lake Qn-Grbg-SA

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Hondo Oil & Gas Company	
3. Address of Operator P. O. Box 2208, Roswell, NM 88202	
4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 7 Township 18S Range 27E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3307' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
OTHER: Perf & Stimulate the Lower S.A. zone <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We would like to begin the following procedure 02/10/92.

- (1.) POH w/ rods & pump.
- (2.) POH w/ tbg.
- (3.) PU 4 3/4" bit & DC's & 2 7/8" work string & TIH.
- (4.) Drill shoe jt from 1767'-1803' w/ 2% KCL wtr & 1 gal/1000 surfactant.
- (5.) POH & LD bit & DC's.
- (6.) Run GR-CNL-CCL log from 1803'-1000'.
- (7.) Perf S. A. "C" Zone from 1772'-1784' w/ 1 JSPF 13 holes.
- (8.) TIH w/ pkr & acidize perfs 1772'-1784'.
- (9.) Swab test.
- (10.) Frac S. A. "C" Zone perfs.
- (11.) Clean out sand fill.
- (12.) Run pump & rods & test.

RECEIVED  
FEB 13 1992  
O. C. D.  
ARTESIA OFFICE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE E. L. Buttross, Jr. TITLE Petroleum Engineer DATE 02/06/92  
(505) 625-6732  
TELEPHONE NO.

TYPE OR PRINT NAME E. L. Buttross, Jr.

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE FEB 21 1992

CONDITIONS OF APPROVAL, IF ANY: