

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | 3 |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

FEB 18 1970

O.C.C.

SUNDRY NOTICES AND REPORTS ON WELLS OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|--|--|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/> | | 5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> |
| 2. Name of Operator Atlantic Richfield Company | | 5. State Oil & Gas Lease No. |
| 3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201 | | 7. Unit Agreement Name West Red Lake Unit |
| 4. Location of Well UNIT LETTER J 2310 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 18-S RANGE 27-E NMPM. | | 8. Farm or Lease Name West Red Lake Unit |
| | | 9. Well No. 10 |
| | | 10. Field and Pool, or Wildcat Red Lake-Grayburg, S. |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3311' DF | | 12. County Eddy |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To prepare this well for waterflood response, we propose the following work:

1. Perforate from 1034' to 1038' & 1042' to 1047' w/2 JSPF.
2. Treat w/750 gallons 15% HCl acid, ball sealers & 10,000 gallons of slick fresh water containing 10,000# of 20/40 sand.
3. Add perforations from 1642-48, 1662-64 & 1669-74 w/2 JSPF; treat w/1000 gallons 15% HCl acid & 20,000 gallons of slick fresh water containing 20,000# of 20/40 sand.

Return well to rod pump. Work to start about 3/1/70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A.D. Bratches

TITLE Dist. Drlg. Supervisor

DATE 2-16-70

APPROVED BY W.A. Gressett

TITLE OIL AND GAS INSPECTOR

DATE FEB 19 1970

CONDITIONS OF APPROVAL, IF ANY: