

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE MANNER INDICATED
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-025604

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	3. ADDRESS OF OPERATOR Box 68 Hobbs NM 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL x 1980' FEL Sec 9 (Unit G, SE/4 NE/4)	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME MALCO "G" FEDERAL	9. WELL NO. 10	10. FIELD AND POOL, OR WILDCAT EMPIRE ABO	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 9-18-27 NMPM	12. COUNTY OR PARISH EDDY	13. STATE NM
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3547' R.D.B.									

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

In an effort to reduce GOR the following work is proposed:

Perforate 4 1/2" casing w/4JS @ interval 5400-5401.
Set retrievable BP at 5450 + cap w/10' sand.
Squeeze behind 4 1/2" w/ 200# Incor + 0.5% Halad 9.
Drill + cleanout and retrieve BP. Restore to production.

TD - 5700'

PERFS: 5520-30, 42-5A, 64-70, 82-9A.

PBD - 5664'

4 1/2" CSA 5700

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Engineer

DATE

9-13-66

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

of 4- USGS- Act
1- NSW
1- SUSP
1- RRY
1- HONDO

*See Instructions on Reverse Side

