	7.15F
LALL CLUE COPY	z/SF Zilie√
Form 9–331 Dec, 1973	Form Approved. Budget Bureau No. 42R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	LC-065478 b
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	Z. UNIT AGREEMENT NAME Empire Abo Pressure
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Maintenance_Project
	8. FARM OR LEASE NAME Empire Abo Unit "N"
1. oil gas development well well other	9. WELL NO.
2. NAME OF OPERATOR ARCO Oil & Gas Company	
Division of Atlantic Richfield Company $$ 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Empire Abo
P. O. Box 1710, Hobbs, New Mexico 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1650' FNL & 2310' FEL	AREA 10-18S-27E
below.) 1000 FNL & 2010 FEL AT SURFACE:	10-103-27E 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: As Above	Eddy N M
AT TOTAL DEPTH: As Above 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
DEQUERT FOR APPROVAL TO. SUBSEQUENT REPORT OF	3471' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	
	IVED
SHOOT OR ACIDIZE	
PULL OR ALTER CASING	
CHANGE ZONES	CAL SURVEY
ABANDON* ARTESIA, NE	EW MEXICO
	a all participant details, and give participant dates
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent.	irectionally drilled, give subsurface locations and it to this work.)*
<ol> <li>Rigged up on 9/23/80, killed well, POH w/ rods &amp; pump, installed BOP.</li> <li>RIH w/ RBP, set @ 62'. Pressured wellhead to 1500#, leaked 1" stream out well</li> </ol>	
2. RIH w/ RBP, set @ 62'. Pressured wellhead to 1500#, leaked 1 stream out well head around ring gasket. Replaced ring gasket. Pressured up wellhead, leaked off. POH w/ RBP.	
3. Removed top wellhead spool, replace ring gasket, installed wellhead & BOP's.	
4. RIH w/ RBP, set BP @ 610'. Pressured up csg & wellhead to 1500# for 30 mins, OK.	
5. Re-set RBP @ 5845'. Set pkr @ 5783'. Press tested tbg to 2000#, tbg/csg annulus to 1500# for 30 mins, OK. POH w/ pkr & RBP.	
6. RIH w/ comp assy. Returned well to production on 10/1/80.	
FINAL REPORT.	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. Thereby certify that the foregoing is true and correct	
SIGNED Jerry W. Schmidt TITLE Dist. Drlg. S (This space for Federal or State off	Supt. DATE10/15/80
(This space for Federal or State off	ice use)
APPROVED BY	
CONDITIONS OF APPROVAL, IF ANY:	ACCLERE
	00T 0 1 1090
*See Instructions on Reverse :	U.S. GEOLOGICAL SURVEY
	ROSWELL, NEW MEXICO

ŧ,

- 3