

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM6852

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "EA"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Empire Abo Field

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 12, T-18-S,
R-27-E.

12. COUNTY OR PARISH

13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Robert G. Cox

3. ADDRESS OF OPERATOR

6222 No. Central Expressway, Dallas, Texas 75206

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

330' from north and west lines of Section 12,
T-18S, R-27-E, Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3609 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Sept. 25-27, 1968. Drilled cement plugs from 1328'-1530', 2315'-2440', 3174'-3260', 3448'-3510'. Ran drill pipe to 4098.74' and set on 5-1/2" casing. Pulled drill pipe and bit out of hole and went into hole with 6-3/8" O.D. x 6' washovershoe and flat bottom mill. Touched fish at 4098'-74' and washed over casing. Milled 1 foot off top of 5-1/2" casing to get smooth top. Pulled flat mill and went back in hole with dress off mill to chamfer top of casing.

Ran 5-1/2" casing as follows:

1 - 5-1/2" Bowen Lead Seal Casing Patch	2.12'
132 jts.-5-1/2", 14#, J-55, smls. New Casing	4088.87'
Total	4090.99'
Less Cut Off Jt. #132	2.11'
	4088.88'

Set Below Top R.D.B. 11.00

Set Casing Patch with 15,000 lbs. tension 4099.88'

Pressured casing to 1500 psi and casing pressure held.

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert G. Cox

TITLE

Operator

DATE

Nov. 1, 1968

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

NOV 5 1968
R. L. BEAMAN
ACTING DISTRICT MANAGER

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1983-O-685229

GPO 837-499

807-351