

NO. OF COPIES RECEIVED	55
DISTRIBUTION	
SANTA FE	
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	21

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

OCT 20 1975

O. C. C.

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B - 10036</b>
7. Unit Agreement Name <b>Artesia State Unit</b>
8. Farm or Lease Name <b>Tract No. 10</b>
9. Well No. <b>2</b>
10. Field and Pool, or Wildcat <b>Artesia</b>
12. County <b>Eddy</b>

**SUNDRIY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Water supply well**

2. Name of Operator  
**Anadarko Production Company /**

3. Address of Operator  
**P. O. Box 67, Loco Hills, New Mexico 88255**

4. Location of Well  
UNIT LETTER **P**, **990** FEET FROM THE **South** LINE AND **990** FEET FROM  
THE **East** LINE, SECTION **14** TOWNSHIP **18S** RANGE **27E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
**3514 GL**

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	<b>Re-PLUG AND ABANDONMENT</b> <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Tagged old cement plug @ 450'.
2. Shot 7" casing @ 425'; did not pull.
3. Pumped 100 sx cement plug @ 450'.
4. Shut in 17 hours; wait on cement; tagged top of plug @ 46'.
5. Pumped 10 sx cement plug from 46' to surface.
6. Erected dry hole marker; closed pits and cleaned location on 9-7-75.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed by Jerry E. Buckles TITLE Area Supervisor DATE October 13, 1975

APPROVED BY Lois R. Burgeton TITLE OIL AND GAS INSPECTOR DATE OCT 22 1975

CONDITIONS OF APPROVAL, IF ANY: