

NO. OF COPIES RECEIVED	1
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

OCT 20 1975

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B - 10036
7. Unit Agreement Name Artesia State Unit
8. Farm or Lease Name Tract No. 10
9. Well No. 3
10. Field and Pool, or Wildcat Artesia
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Supply Well
2. Name of Operator Anadarko Production Company /
3. Address of Operator P. O. Box 67, Loco Hills, New Mexico 88255
4. Location of Well UNIT LETTER P 990 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 18 S RANGE 27E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3504' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Tagged old cement plug @ 400'.
2. Pumped 80 barrels of fresh water without circulation.
3. Pumped 40 barrels of mud without circulation.
4. Pumped 80 sx cement plug @ 400'.
5. Shut in 17 hours; wait on cement; tagged top of plug @ 225'.
6. Pumped 45 sx cement plug @ 225' without circulation.
7. Shut in 4 hours; wait on cement; tagged top of plug @ 212'.
8. Pumped 50 sx cement plug @ 212'.
9. Shut in 17 hours; wait on cement; tagged top of plug @ 130'.
10. Pumped 50 sx cement from 130' to surface.
11. Erected dry hole marker, closed pits and cleaned location on 8-22-75.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed by Jerry E. Buckles TITLE Area Supervisor DATE October 13, 1975

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE OCT 22 1975

CONDITIONS OF APPROVAL, IF ANY: