

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SAFETY	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	21

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 8 1975

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B - 10456
7. Unit Agreement Name Artesia State Unit
8. Farm or Lease Name Tract No 1 5
9. Well No. 4
10. Field and Pool, or Wildcat W. D. Pool
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. C.

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DEEPER FORM. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Anadarko Production Company ✓
3. Address of Operator P. O. Box 67, Loco Hills, New Mexico 88255
4. Location of Well UNIT LETTER I 330 FEET FROM THE East LINE AND 1650 FEET FROM THE South LINE, SECTION 14 TOWNSHIP 18 S RANGE 27 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3493 GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 100 sx cement plug in open hole from T. D. 1835' to bottom of 7" casing @ 1727' and 50' into 7" casing @ 1677'.
2. Shut in 4 hours; wait on cement; tag plug.
3. Shoot 7" casing off @ 1500'.
4. Pull 7" casing.
5. Spot 35 sx plug of cement through Queen Section 1500' to 1400'.
6. Spot 6 sx mud.
7. Spot 35 sx cement plug through Seven Rivers Section 950' to 850'.
8. Spot 8 sx mud.
9. Spot 35 sx cement plug 50' in and 50' out of 10" casing @ 258'.
10. Spot 10 sx cement plug at surface.
11. Ereet dry hole marker, close pits and clean location.

10" - 258
7" - 1727 - 50

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by
Jerry E. Buckles

SIGNED

TITLE **Area Supervisor**

DATE **July 3, 1975**

APPROVED BY

W. A. Gussert

TITLE **SUPERVISOR, DISTRICT II**

DATE **JUL 9 1975**

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging