NUMBER OF	COPIES ECEIVED		······				<u></u>			
U.8.6.5.	NEW MEXICO UIL CONSERVATION COMMISSION FORM C. 103									
LAND OFFICE LAND OFFICE TRANSPORTER OIL GROV 3-55) MISCELLANEOUS REPORTS ON WELLS PROPATION OFFICE										
Corsenation orelics Corsenation Correct Commission Rule JUN 6 1962										
HIMRIE OTI & REFINITIO COMPANY										
Box 2,47, HOBDS, New Mexico U. L. D										
	alk Bluff Dre	aw Unit	14	"F"	16	T-18		Range. R	A, OFFICE -27-E	
Date Work H 5-2, 5		Pool	4 ho			County		•		
5-2, 5-27-63 Empire Abo THIS IS A REPORT OF: (Check appropriate block)										
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):										
Plugging XX Remedial Work										
Detailed account of work done, nature and quantity of materials used, and results obtained.										
1. Kill well. Pull rods and tubing. 2. Perforated 4-1/2" casing at 5461. 5482. 5501.										
5505, 5516, 5519, 5524, 5529, 5537 and 5542 with 1 shot per interval by Lane Wells.										
3. Ran tubing with retreivable bridge plug and full bore cementer (Packer). Set plug at 5562. Unable to load casing with water indicating communications between old and										
new perforations. Set packer at 5554 to check plug in blank pipe. Held ok with 2600#										
pressure. Reset packer at 5426. Loaded casing with water. Tested ok. 4. Mixed										
350# moth balls with 8 barrels jelled slick water and pumped into above mentioned perf- orations. Well went on vacuum. 5. Mixed 650# moth balls with 8 barrels water and										
pumped into above mentioned perforations. Got block. Unable to break down perforations										
with 6000# pressure. Unable to circulate out moth balls. Pulled tubing and packer										
o. Circulated out moth balls to 5562. Well on vacuum. 7. Acidized perforations (above										
mentioned) with 15,000 gallons regular 15% low fluid loss acid with an average injection rate of 6 BPM. Max pressure 4000#. Treatment by the Western Company. 8. Pulled										
retreivable bridge plug and tubing. 9. Ran tubing, pump and rods. Tested. 10. Well										
recompleted as a pumping oil well. 11. Unsuccessful.										
Witnessed by Position Company   J. C. Sherrill Field Superintendent HUMBLE OIL & REFINING COMPANY										
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY										
ORIGINAL WELL DATA										
3498		5700	567	73		Producing Interval 5582-5600		Comp	Completion Date 7-23-60	
Tubing Diameter Tubing Depth 2" Unknown				Oil String Diameter Oil String Depth						
Perforated Interval(s) 4-1/2 5699										
5582-5600										
Open Hole In	Produci	Producing Formation(s) Abo								
RESULTS OF WORKOVER										
Test	Date of Test	Oil Production BPD	Gas Produ MCFP		Water Pr BI	oduction D	GOR Cubic feet/Bbl	C	Gas Well Potential MCFPD	
Before Workover	4-4-63	41	21	-		7	467		-	
After Workover	5-28-63	41	69			14	1683			
OIL CONSERVATION COMMISSION I hereby certify that the information given above is true and complete to the best of my knowledge.										
					SIGNED: E. S. DAVIS					
Title		Position Agent								
Date JUN # 1963					Agent Company					
				LUM	HUMBLE OIL & REFINING COMPANY					