Form 3160-5

Form approved. Budget Bureau No. 1004-013

(November 1983) SUBMIT IN LICATE JNITED STATES (Other instru... ms on re-(Formerly 9-331) Expires August 31, 1985 verse side) DEPARTMENT OF THE INTERIOR 5. LEASE DESIGNATION AND SERIAL NO. **BUREAU OF LAND MANAGEMENT** NM-29276 SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED 6. IF INDIAN, ALLOTTEE OR TRIBE NAME (Do not use this form for proposals to drill or deepen or plug back to a different reservoir. Use Form USE "APPLICATION FOR PERMIT -- for such proposals.) 7. UNIT AGREEMENT NAME OIL GAS WELL X WBLL other 2. NAME OF OPERATOR 8. FARM OR LEASE NAME ARCO Oil and Gas Company DEFICE Empire Abo Unit "R" 3. ADDRESS OF OPERATOR 9. WELL NO. P. O. Box 1610, Midland, Texas 79702 4. LOCATION OF WELL (Report location in accordance with any State requirements." 10. FIELD AND POOL, OR WILDCAT See also space 17 below.) **Empire Abo** At surface 1980 FNL & 1980 FEL (Unit Letter G) 11. SEC., T.,R.,M., OR BLK. AND SURVEY OR AREA 17-18S-27E 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RF, GR, ect.) 13. STATE 12. COUNTY OR PARISH 30-015-00914 3436 DF Eddy NM 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT* REPAIR WELL CHANGE PLANS Recomplete Abo (NOTE: Report results of multiple completion on Well (Other) Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11-27-89. RUPU. DO CIPB at 4998. Swab Abo perfs 5392-5454. Acidize w/3000 gals. Swab back load flow test. Set RBP at 538 Perf Abo f/5320-5336 & 5350-5360. Acidize w/900 gals. Swab test. POH w/RBP. RIH w/2 3/8 tbg to 5528. 12-08-89. RDPU. 12-18-89. RUPU. POH w/tbg. set CIBP at 5277. Dug out wellhead. Found holes in csg 3' below GL. Replace 4' section of 8 5/8 csg. Press test 5 1/2" csg. OK. Press test 8 5/8 csg. OK. DO CIBP. RIH w/CA: 2 3/8 tbg to 5528, rods & pump. 01-06-90. RDPU. 01-18-90. In 24 hrs pmpd 54 BO, 68 BW, 106 MCF. I hereby certify that the foregoing is true and correct 1-19-90 (This space for Federal or State office use) APPROVED BY CONDITIONS FOR APPROVAL, IF ANY: