FORM 9:331A (FEB. 1951)

APPLOVED

OUC 2 960

ONES A KNAUF

ENGINEER SINDRY

N. M. O. C. C. COPY.
(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

LAND OFFICE N. M. O4175 LE

LEASE NO. 231616E

UNIT

NOTICE OF IN

NDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DEILL NOTICE OF INTENTION TO CHANGE PLANS NOTICE OF INTENTION TO TEST WATER SHUT-OFF NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO FULL OR ALTER CASING. NOTICE OF INTENTION TO ABANDON WELL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
---	--	-------------------------------------	---

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

ABO	CHALK	BLUFF	DRAW	UNIT
-----	-------	-------	------	------

HOBBS, NEW MEXICO SEPTEMBER 12, 19 60

WELL NO. 12 IS LOCATED.	_ <u>5501_</u> FT	FROM (N) LINE AT	ND 350 FT. FROM (E) LINE OF SEC.17	
NE/4 of NE/4 of SEC. 17	18-3	27-E		
(% SEC. AND SEC. NO.)	(TIVP.)	(RANGE)	(MERIDIAN)	
EMPIGE ABO	Æ D I		NEW MEXICO	
(FIELD)	(COUNTY OR SUBDIVISION)		(STATE OR TERRITORY)	

THE ELEVATION OF THE DERRICK FLOOR ABOVE SEA LEVEL IS 3483 FT.

DETAILS OF WORK

(STATE NAMES OF AND EXPECTED DEPTHS TO GRIEGTIVE SANDS; SHOW SIZES, WEIGHTS, AND LENGTHS OF PROPOSED CASINGS; INDICATE MUDDING JOBS, CEMENTING POINTS, AND ALL OTHER IMPORTANT PROPOSED WORK.)

Set cament plug in 4-1/2" (oil string) casing from 1643 to 1543' with 15 sacks cement. Out off wellhead. Set cement plug from 29' to surface with 10 sacks. Welded cap on top and install dry hole marker as required by NHOCC. Verbal approval per in Knauf 9-r=60. Well plugged & abandoned.

SEP 2 11988

1 UNDERSTAND THAT THIS . LAN OF WORK MUST RECEIVE APPROVAL IN WRITING BY	THE GEOLOGICAL SURVEY BEADRE	OPERATIONS MAY BE COMMENCED.
COMPANY Humble Oil & Refining Company		
ADDRESS Box 2347, Hobbs, Hew lexico	ORIGINAL SIGNED	Signature and the
		. 4
	Title Agent	