

NO. OF COPIES RECEIVED	11
DISTRIBUTION	
SANITARY	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	21

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 8 1975

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT DEPTH OR DIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator <b>Anadarko Production Company</b>	5. State Oil & Gas Lease No. <b>B - 11083</b>
3. Address of Operator <b>P. O. Box 67, Loco Hills, New Mexico 88255</b>	7. Unit Agreement Name <b>Artesia State Unit</b>
4. Location of Well UNIT LETTER <b>B</b> , <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>1650</b> FEET FROM THE <b>East</b> LINE, SECTION <b>23</b> TOWNSHIP <b>18 S</b> RANGE <b>27 E</b> NMPM.	8. Farm or Lease Name <b>Tract #7</b>
	9. Well No. <b>3</b>
	10. Field and Pool, or Wildcat <b>Artesia</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3510</b>	12. County <b>Eddy</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 100 sx cement plug in open hole from TD 1925' to 1650', this would be 50' above Loco Hills Section of Grayburg.
2. Shut in 4 hours; wait on cement; tag plug.
3. Spot 2 sx mud.
4. Spot 35 sx cement plug in open hole from 1525' to 1425', this would be 50' below and 50' above Queen Section.
5. Spot 6 sx mud.
6. Spot 35 sx cement plug in open hole from 1000' to 900', this would be 50' below and 50' above Seven Rivers Section.
7. Spot 6 sx mud.
8. Spot 35 sx cement plug 50' in and 50' out of 8" casing @ 487'.
9. Spot 10 sx cement plug at surface.
10. Erect dry hole marker, close pits and clean location.

8"-487-50

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed by Jerry E. Buckles TITLE Area Supervisor DATE July 3, 1975

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUL 9 1975

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

*plugging*