

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JAN 12 1971
ARTESIA, N.M.

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. B-8156	
7. Unit Agreement Name	
8. Farm or Lease Name State BW	
9. Well No. 12	
10. Field and Pool, or Wildcat Artesia (Q.G.-SA)	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Cities Service Oil Company
3. Address of Operator Box 69 - Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER I , 2970 FEET FROM THE North LINE AND 960 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 18S RANGE 27E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was plugged and abandoned on 4/2/69 in the following manner:

1. Set a 30 sack cement plug @ 1934-2034.
2. Loaded hole with mud laden fluid.
3. Set a 30 sack cement plug @ top of the Queen @ 1350-1250.
4. Set a 30 sack cement plug @ 525-435 (1/2 in and 1/2 out of 8 5/8" casing set and cemented @ 480)
5. Set a 10 sack cement surface plug @ 30-0' with a 4" marker extending 4' above the surface to designate a P & A location.
6. Location has been cleaned of all debris and equipment and is ready for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____	TITLE District Admin. Supervisor	DATE 1/6/71
APPROVED BY _____	TITLE OIL AND GAS INSPECTOR	DATE JAN 14 1971
CONDITIONS OF APPROVAL, IF ANY:		