

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

AUG 28 1980

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDY NOTICES AND REPORTS ON WELLS</p> <p>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator Yates Drilling Company</p>		<p>8. Farm or Lease Name Artesia Metex Unit</p>
<p>3. Address of Operator 207 So. 4th Street, Artesia, NM 88210</p>		<p>9. Well No. #54</p>
<p>4. Location of Well UNIT LETTER O 990 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 18S RANGE 27E NMPM.</p>		<p>10. Field and Pool, or Wildcat Artesia Grqb. SA</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3548 GR</p>		<p>12. County Eddy</p>

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input checked="" type="checkbox"/> Bradenhead Test</p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dug out old tubing head left on surface pipe. Welded 4½" casing to old tubing head. Installed high pressure 2" valve. Swidged down with tapped ball plug to ½" needle valve above ground level. Shut in 24 hours before inspection. No pressure on surface pipe or 4½ casing. Tubing pressure 1080 lbs. Inspected by Mr. Weaver, OCD, Artesia.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Brian P. Harris TITLE Drilling Supervisor DATE August 28, 1980

APPROVED BY B.W. Weaver TITLE OIL AND GAS INSPECTOR DATE SEP 8 - 1980

CONDITIONS OF APPROVAL, IF ANY: