June 16, 1961

Receiver 19, 19, 61

R. L. Heinsch % Simms and Reese Oil Co. 102 South Second Artesia, New Mexico

Re: Western Development Well # 2, Unit N, Sec. 26-18S-27E, Undesignated Artesia Pool.

Dear Mr. Heinsch:

We are returning the enclosed Forms C-103 on the above-captioned well in order that you may fill in the details of the work.

We need the "waiting on cement" time, and who did the sementings

Very truly yours,

OIL CONSERVATION COMMISSION

MLA/sa Encl: 2 sets Form C-103 M. L. Armstrong Supervisor, District No. 2 fune Lo, 1921

1. L. Asinsch 1 Simme sud Amess 011 00. 102 South Second Artesis, New Yexico

det Mentern Sevelopment Well 2 2, Unit K, Sec. 26-185-278, Indestanated Artests Fool.

nisente: .TA 1800

we are returning the enclosed Forms C-103 on the spove-captioned well in order that you may fill in the details of the work.

We need the "waiting on cement" time, and who der for for former with

very truly yours.

ULL CORBERVATION OCAMIESTON

SLA/88 Encl: 2 sets room 3-103

S. .. Arastrons Supervisor, Matrict No. 2