Submit 3 CopiesState of New Mexicoto AppropriateEDistrict OfficeE	partment Form C-103 Revised 1-1-89			
DISTRICT I P.O. Box 1980, Hobbs NM 88240 DISTRICT II Sulf South First Artacia NM 88210 Santa Fe, New Mexico 87505	SION WELL API NO. 30-015-00966			
DISTRICT III 1000 Rio Brazos Rd Aztec, NM 87410	5. Indicate Type of Lease STATE STATE FEE			
	6. State Oil & Gas Lease No. B-11088			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).	K TO A 7. Lease Name or Unit Agreement Name			
1. Type Of Well: OIL GAS OTHER	Artesia Metex Unit			
2. Name of Operator Mack Energy Corporation	8.Well No.			
3. Address of Operator	513			
P.O. Box 960, Artesia, NM 88211-0960 4. Well Location Audress of Operator P.EUEIVED P.EUEIVED P. Bool name or Wildcat Artesia Gueen Grayburg SA				
Unit Letter P : S Line an	id Feet From The E Line			
Section 26 Township 18S Range 24	Eddy County			
10. Elevation (Show whether DF, RKB, RT, C 3552	GR, etc.) (Constraint) (Const			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE	E DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING CASING TES	ST AND CEMENT JOB			
OTHER: OTHER	X			

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/21/96 RU Pump stuck. Strip rods & tbg out of hole. Laid down 47 jts 2 7/8" tbg & 59 7/8" rods. Severe scale problem. Inside & outside of tbg.

11/18/96 Rig up RIH with tubing clean out tag fill at 1602 ft clean out to hard spot at 1785ft with 2 7/8" tubing, notched collar and SN, pull 2 jts land tubing at 1720. 54 jts 2 7/8" tubing SN at 1720ft pumped with BJ Service 1000 gals 15% NE went on a vacuun, RIH with 71-7/8" rods, 2 1/2 x 2 x 12ft RWTC rag ring pump, flange up, clean up rig down.

12/11/96 AM rig up pull rods and pump, laydown, pull 2 7/8" tubing, break well head off, clean up rig down, SHUT IN WELL and PREPARE TO PLUG. Well pumping all water.

I bereby certify that the information abo SIGNATURE	ve is true and complete to the best of my knowledg	e and belief. 	0	DATE 12/4/47
TYPE OR PRINT NAME				TELEPHONE NO. (505)748-1288
(This space for State Use)	SUPERVISOR, DISTRICT II		DEC - 9 1997	
APPROVED BY		TITLE	DEC 0 1337	DATE