

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-01192
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 648-131
7. Lease Name or Unit Agreement Name Artesia Metex Unit
8. Well No 28
9. Pool name or Wildcat Artesia-QN-GR-SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3566'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Water Injection Well
2. Name of Operator SDX RESOURCES, INC.
3. Address of Operator P. O. BOX 5061 MIDLAND, TX 79704
4. Well Location Unit Letter C : 990 Feet From The North Line and 2310 Feet From The West Line Section 25 Township 18S Range 27E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- 5/10/95 RU Mayo Marrs unit and released packer and TOH. Set CIBP @ 1840' and capped w/35' cement. Circulated hole w/mud laden fluid & TOH. TIH, cu 2nd casing @ 1504' & pulled casing. TIH & spotted 30 sx plug @ 1554'. Tagged top of plug @ 1504'.
- 5/11/95 Spotted 30 sx plug at 900'-800'. Spotted 40 sx plug @ 552'. Tagged top of plug @ 400'.
- 5/12/95 Set 10 sx surface plug & installed dry hole marker. Cleaned location and removed anchors. Job witnessed by Mike Stuffield, NMOCD. P&A complete.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE  TITLE VICE PRESIDENT

DATE 5/24/95

TYPE OR PRINT NAME JOHN POOL

TELEPHONE NO (915) 685-1761

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY